Profile/Photo Observation Report



Date: 04/16/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 184.7 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-404-020-021 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN N WABASH ST & N Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-404-020 DS MH: M-404-021 Total Length Surveyed (ft): 66.2

3722 2.23 29.00 O&M Index: O&M Quick: O&M Rating: 2.00 2600 12.00 Structural Quick: Structural Rating: Structural Index: 2.16 3728 41.00 Overall Quick: Overall Rating: Overall Index:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-404-020

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: TBI

Description: **Tap Break-in Intruding**

Distance (ft): 6.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 1

Clock To:

1st Value: 4.000 2nd Value: 2.000

Value Percent: Continuous Index: Within 8" of Joint:

Code: MWLS

Description: Water Level Sag

Distance (ft): 22.0 Structural Grade: 2

O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 28.3
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 8

Clock To: 4

1st Value:

2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: YES

Code: MWLS

Description: Water Level Sag

Distance (ft): 31.3
Structural Grade: 2
O&M Grade: 3

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:

Code: TBI

Description: Tap Break-in Intruding



Distance (ft): 32.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9

Clock To:


 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:

Code: **MWLS**

Description: **Water Level Sag**



42.8 Structural Grade: 2 3 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: F01 Within 8" of Joint: NO

Remarks:

RFJ Code:

Description: **Roots Fine Joint**




Distance (ft): 44.5 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent:

Within 8" of Joint: YES

Remarks:

Continuous Index:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 49.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent:

Continuous Index: S02
Within 8" of Joint: YES

Remarks:

Code: MWLS

Description: Water Level Sag



Distance (ft): 49.9
Structural Grade: 2
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S03
Within 8" of Joint: NO



Code:

RFJ

Roots Fine Joint



Distance (ft): 63.6
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 8

Clock To: 4

1st Value: 2nd Value: Value Percent:

Continuous Index: F02
Within 8" of Joint: YES

Remarks:

Code: MWLS

Description: Water Level Sag



Distance (ft): 63.6
Structural Grade: 2
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F03
Within 8" of Joint: NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 66.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped