
Date:	04/16/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	361.7	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honu	PSR:	P-404-030-029
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	Summerlin	Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details:			Direction of Surv	ey: Downstream	
US MH: N	1-404-029	DS MH:	M-404-030	Total Length Surveyed (ft)	: <b>173.9</b>
D&M Index:	4.00	O&M Quick:	4F0	0 O&M Rating:	140.00
Structural Index:	0.00	Structural Qu	uick: 000		0.00
Overall Index:	4.00	Overall Quick			140.00





Code: Description:	MCU Camera Underwater
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	



Code: Description:

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-404-029

AMH

Manhole



## Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 15.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code:MCUDescription:Camera Underwater

Distance (ft):	173.9
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	

Code: Description: MSA Abandoned Survey



Distance (ft):	173.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera underwater