## **Profile/Photo Observation Report**



Date: 09/09/2021 Weather: Coding: **PACP 7.0** Pipe Length (ft): 355.0 Owner: **City of Hobart** Pre Clean: **Light Cleaning** P.O.#: YES502259 Surveyor: S. Bucklin PSR: P-404-030-029

Customer: City of Hobart Clean Date: 09/09/2021 Shape: C

Street: North Clark Street Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Local rural streets with light traffic, t Tape/Media #:

Purpose:Routine AssessmentDia/Height:12"Use:Sanitary Sewage PipeMaterial:VCP

Drain Area: Lining: **None** 

Category: NA


Comment:

Location Details: Direction of Survey: Upstream

US MH: M-404-029 DS MH: M-404-030 Total Length Surveyed (ft): 355.0

O&M Index:	2.44	O&M Quick:	4132	O&M Rating:	22.00
Structural Index:	2.13	Structural Quick:	422D	Structural Rating:	64.00
Overall Index:	2.21	Overall Quick:	4332	Overall Rating:	86.00

Posit	ion Code	Observation	Video (sec)	Grade
404-030				
0.	AMH	Manhole	1	NA
0.	MWL	Miscellaneous Water Level	68	NA
9.7	TF	Tap Factory	157	NA
11.7	TF	Tap Factory	203	NA
36.2	MWLS(S01)	Miscellaneous Water Level Sag	290	S 2
63.0	MWLS(F01)	Miscellaneous Water Level Sag	369	S 2
65.0	TF	Tap Factory	389	NA
72.1	TF	Tap Factory	431	NA
102.0	CS	Crack Spiral	556	S 2
102.0	DAE	Deposits Attached Encrustation	587	M 2
102.0	IDB	Infiltration Dripper Barrel	609	M 3
103.3	DAE	Deposits Attached Encrustation	657	M 2
103.3	IRJ	Infiltration Runner Joint	670	M 4
123.6	i ISZ	Intruding Sealing Material Other	759	M 2
135.3	TF	Tap Factory	811	NA
170.8	В	Broken	984	S 4
170.8	DAE	Deposits Attached Encrustation	1014	M 2
171.5	MWLS(S02)	Miscellaneous Water Level Sag	1051	S 2
184.6	MWLS(F02)	Miscellaneous Water Level Sag	1117	S 2
209.1	. MWLS(S03)	Miscellaneous Water Level Sag	1216	S 2
216.5	TF	Tap Factory	1258	NA
226.4	TF	Tap Factory	1342	NA
255.5	ISSRH	Intruding Sealing Material Sealing Ring Hanging	1488	M 2
258.1	. DSZ	Deposits Settled Other	1523	M 2
301.5	MWLS(F03)	Miscellaneous Water Level Sag	1695	S 2
309.3	TF	Tap Factory	1734	NA
311.3	TF	Tap Factory	1765	NA
312.0	В	Broken	1797	S 4
312.0	RMJ	Roots Medium Joint	1827	M 3
321.0	MWLS	Miscellaneous Water Level Sag	1871	S 2
355.0	AMH	Manhole	2034	NA




Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-404-030



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0


Clock Start/From:

Clock To:
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 9.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 11.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2


Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 36.2
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: MWLS


Description: Miscellaneous Water Level Sag

Distance (ft): 63.0
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F01
Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 65.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 72.1
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: CS

Description: Crack Spiral


Distance (ft): 102.0
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 11
Clock To: 1

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 102.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 4
1st Value:

2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IDB

Description: Infiltration Dripper Barrel

Distance (ft): 102.0
Structural Grade: 0
O&M Grade: 3


Clock Start/From: 1
Clock To: 2

1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

NO



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 103.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10
Clock To: 4
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IRJ

Description: Infiltration Runner Joint


Distance (ft): 103.3
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 1

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: ISZ

Description: Intruding Sealing Material Other

Distance (ft): 123.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To: 10
1st Value:

1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks: JOINT SEALING MATERIAL BUT

DOESNT LOOK TO HAVE ANY MISSIN



Description: Tap Factory

Distance (ft): 135.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: B
Description: Broken

Distance (ft): 170.8

Structural Grade: 4

O&M Grade: 0

Clock Start/From: 9


Clock To: 3

1st Value: 2

2nd Value: Value Percent: Continuous Index:

Remarks:

Within 8" of Joint:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 170.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10
Clock To: 2


1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: MWLS


Description: Miscellaneous Water Level Sag

Distance (ft): 171.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: NO



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 184.6
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F02
Within 8" of Joint: NO

Remarks:



Code: MWLS


Description: Miscellaneous Water Level Sag

Distance (ft): 209.1
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S03
Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 216.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: FIRST JOINT BACK HAS

**ENCRUSTATION** 



Code: **TF** 

Description: Tap Factory


Distance (ft): 226.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: ISSRH

Description: Intruding Sealing Material Sealing

**Ring Hanging** 

Distance (ft): 255.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 10

1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: DSZ

Description: Deposits Settled Other

Distance (ft): 258.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks: CUT ROOTS, TP AND SEWER DEBRIS



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 301.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory


Distance (ft): 309.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Description: Tap Factory

Distance (ft): 311.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ROOTS GROWING IN THE TAP

YES



Code: B


Description: Broken

Distance (ft): 312.0
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 3
Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 312.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 10

1st Value:

2nd Value: Value Percent:


5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 321.0
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: AMH
Description: Manhole

Distance (ft): 355.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: M-404-029

NO