Profile/Photo Observation Report



Date: **04/15/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 199.5 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Selasie Honu PSR: P-405-003-004

Customer: Clean Date: 01/01/1900 Shape: C

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Flow direction is marked wrong.

Location Details: Direction of Survey: **Downstream**

US MH: M-405-004 DS MH: M-405-003 Total Length Surveyed (ft): 12.8

3300 3.00 9.00 O&M Index: O&M Quick: O&M Rating: 2.00 2300 6.00 Structural Quick: Structural Rating: Structural Index: 2.50 3323 15.00 Overall Quick: Overall Rating: Overall Index:

Position	Code	Observation	Video (sec)	Grade
004				
.0	MGO	General Observation	12	NA
.0	AMH	Manhole	26	NA
0.	MWL	Water Level	37	NA
\.0	MWLS(S01)	Water Level Sag	48	S 2
12.8	MWLS(F01)	Water Level Sag	90	S 2
12.8	MSA	Abandoned Survey	101	NA

Code:

Description:

Remarks:



Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


NO

MGO

General Observation

REAR CAMERA





Code: MWLS

Description: Water Level Sag

Distance (ft): .0
Structural Grade: 2
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:

Code: MWLS

Description: Water Level Sag



Distance (ft): 12.8
Structural Grade: 2
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 12.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: camera underwater

NO