Profile/Photo Observation Report



Date: **04/15/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 310.4 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Selasie Honu PSR: P-405-006-007

Customer: Clean Date: 01/01/1900 Shape: C

Street: S WABASH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment: Flow direction is marked wrong.

Location Details: Direction of Survey: Upstream

US MH: M-405-007 DS MH: M-405-006 Total Length Surveyed (ft): 14.1

3100 3.00 3.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.50 3121 5.00 Overall Quick: Overall Rating: Overall Index:


	Code	Observation	Video (sec)	Grade
405-006				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
3.9	MWLS	Water Level Sag	40	S 2
/14.1	MSA	Abandoned Survey	72	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-405-006

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: **MWLS**

Description: **Water Level Sag**



Distance (ft): 3.9 Structural Grade: 2

O&M Grade: 3 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 14.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped