

Profile/Photo Observation Report




Date:	03/16/2024	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	133.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:		Surveyor:	S. Bucklin	PSR:	P-405-028-027
Customer:	City of Hobart	Clean Date:	10/25/2023	Shape:	C

Street:	W 3RD PL	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Easement/Right of Way	Tape/Media #:	
Purpose:	Sewer System Evaluation Survey (SS)	Dia/Height:	10"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	Cured-In-Place Pipe
Category:	NA		
Comment:			


Location Details:		Direction of Survey:	Downstream
US MH:	M-405-027	DS MH:	M-405-028
		Total Length Surveyed (ft):	104.7

O&M Index:	2.40	O&M Quick:	3321	O&M Rating:	12.00
Structural Index:	3.00	Structural Quick:	3700	Structural Rating:	21.00
Overall Index:	2.75	Overall Quick:	3A21	Overall Rating:	33.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	0	NA
	.0	MWL	Miscellaneous Water Level	85	NA
	10.7	LL	Line Left	152	M 1
	33.4	TBI	Tap Break-in Intruding	371	M 2
	47.9	LFUC	Lining Feature Undercut Service	546	S 3
	48.0	TBD	Tap Break-in/Hammer Defective	567	M 3
	50.9	MWL	Miscellaneous Water Level	603	NA
	66.3	LFUC	Lining Feature Undercut Service	700	S 3
	66.3	TBD	Tap Break-in/Hammer Defective	723	M 3
	68.6	LFUC	Lining Feature Undercut Service	785	S 3
	68.6	TBD	Tap Break-in/Hammer Defective	807	M 3
	83.0	MWLS(S01)	Miscellaneous Water Level Sag	922	S 3
	102.4	MWLS(F01)	Miscellaneous Water Level Sag	1164	S 3
	104.7	AMH	Manhole	1270	NA




Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-405-027



Code: **MWL**
Description: **Miscellaneous Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **LL**
Description: **Line Left**

Distance (ft): **10.7**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **TBI**
Description: **Tap Break-in Intruding**

Distance (ft): **33.4**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **10**
Clock To:
1st Value: **6.000**
2nd Value: **1.000**
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **SERVICE COLLAPSED. SOIL AND GRAVEL VISIBLE.**




Code: **LFUC**
Description: **Lining Feature Undercut Service**


Distance (ft): **47.9**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **1**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code:	TBD
Description:	Tap Break-in/Hammer Defective
Distance (ft):	48.0
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	2
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	Defective




Code:	MWL
Description:	Miscellaneous Water Level
Distance (ft):	50.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: **LFUC**
 Description: **Lining Feature Undercut Service**

Distance (ft): **66.3**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From: **10**
 Clock To: **11**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **TBD**
 Description: **Tap Break-in/Hammer Defective**

Distance (ft): **66.3**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **10**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **CONSTANTLY RUNNING WATER.**




Code: **LFUC**
Description: **Lining Feature Undercut Service**

Distance (ft): **68.6**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **2**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **TBD**
Description: **Tap Break-in/Hammer Defective**

Distance (ft): **68.6**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **3**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **CONSTANTLY RUNNING WATER.**




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **83.0**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **40.000**
Continuous Index: **S01**
Within 8" of Joint: **NO**
Remarks:



Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **102.4**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **40.000**
Continuous Index: **F01**
Within 8" of Joint: **NO**
Remarks:



Code:	AMH
Description:	Manhole
Distance (ft):	104.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-405-028