## **Profile/Photo Observation Report**



Date: 04/23/2018 Weather: **PACP 6.0** Coding:

Pipe Length (ft): 329.0 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Jen Costello PSR: P-405-056-051

Customer: Clean Date: 01/01/1900 Shape:

**SOFTWOOD DR** Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Yard Tape/Media #: Location:

Purpose: **Routine Assessment** Dia/Height: 12" Use: Sanitary Material: **VCP** 

NΑ Drain Area: Lining:

Category: NA

Comment: F\_S\_P\_C at 2 ft grit/ debris. Flow Direction wrong

**Location Details:** Direction of Survey: **Downstream** 

US MH: Total Length Surveyed (ft): M-405-051 DS MH: M-405-056 3.7

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
M(405-)0	51				
	.0	AMH	Manhole	11	NA
	\0	MWL	Water Level	22	NA
- 11	3.7	MSA	Abandoned Survey	41	NA
M 405-0	56				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent:	
Continuous Index: Within 8" of Joint:	NO
Remarks:	M-405-051

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 4


Continuous Index:

Within 8" of Joint:

Remarks:

40.000

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 3.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **DEBRIS UNDER WATER**