
Profile/Ph	oto Observation	Report				RedZone
Date:	04/12/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 244.9	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costel	lo	PSR:	P-407-003-004
Customer:		Clean Date:	01/01/190	0	Shape:	с
Street:	LAKEVIEW DR		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renew	ed:		
Location:	Yard		Tape/Media	#:		
Purpose:	Routine Assessment	t i	Dia/Height:		10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	ls:		Direction of	Survey:	Upstream	
US MH:	M-407-003	DS MH:	M-407-004	-	Total Length Surveyed (ft):	31.5
0&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
tructural Index:	0.00	Structural Qu	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	<:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-407-004



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	TFA Tap Factory Active
Distance (ft):	28.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Thursday, November 16, 2023



Code:MSADescription:Abandoned Survey

Distance (ft):	31.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	DEBRIS UN

NO DEBRIS UNDER WATER