Profile/Photo Observation Report



Date: 04/12/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 280.6 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-407-007-008

Customer: Clean Date: 01/01/1900 Shape: C

Street: LAKESIDE DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA
Comment: Flow direction is marked wrong.

Location Details: Direction of Survey: **Upstream**

US MH: M-407-008 DS MH: M-407-007 Total Length Surveyed (ft): 271.5

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

| Position | Code | Observation | Video (sec) | Grade |
|----------|------|-------------|-------------|-------|
| 407-007 | | | | |
| .0 | AMH | Manhole | 10 | NA |
| 0. | MWL | Water Level | 21 | NA |
| 49.5 | TF | Tap Factory | 133 | NA |
| 52.1 | TF | Tap Factory | 152 | NA |
| 137.8 | TF | Tap Factory | 339 | NA |
| 139.6 | TF | Tap Factory | 357 | NA |
| 203.0 | TF | Tap Factory | 498 | NA |
| 205.7 | TF | Tap Factory | 518 | NA |
| 264.1 | TF | Tap Factory | 650 | NA |
| 266.6 | TF | Tap Factory | 670 | NA |
| 271.5 | AMH | Manhole | 693 | NA |
| | | | | |
| | | | | |

Code:



| Description: | Manhole |
|---------------------|-----------|
| | |
| 76.) | _ |
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-407-007 |
| | |

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


Remarks:

5.000

NO

Code: TF

Description: **Tap Factory**




Distance (ft): 49.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 3

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory


Distance (ft): 52.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 137.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory


Distance (ft): 139.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 203.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory

Distance (ft): 205.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 264.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory

Distance (ft): 266.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 271.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-407-008