Profile/Photo Observation Report



Profile/Prioto Observation Report									
Date:	10/22/2021	Weather:		Coding:	PACP 7.0				
Pipe Length (ft)	: 146.9	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning				
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-503-005-004				
Customer:	City of Hobart	Clean Date:	10/21/2021	Shape:	С				
Street:	West 40th Place		Flow Control:	Not Controlle	d				
City:	Hobart, IN		Year Renewed:						
Location:	Alley		Tape/Media #:						
Purpose:	Routine Assessmen	nt	Dia/Height:	12"					
Use:	Sanitary Sewage Pi	pe	Material:	VCP					
Drain Area:			Lining:	None					
Category:	NA								
Comment:									
Location Details	s:		Direction of Surve	ey: Upstream					
US MH:	M-503-004	DS MH:	M-503-005	Total Length Surveyed (f	t): 146.9				
O&M Index:	1.73	O&M Quick:	3423	O&M Rating:	26.00				
Structural Index:	2.29	Structural Qu	ick: 4133		39.00				
Overall Index:	2.03	Overall Quick	442		65.00				
			·						

	Position	Code	Observation	Video (sec)	Grade
50	3-005				
	.0	АМН	Manhole	2	NA
	0.	MWL	Miscellaneous Water Level	107	NA
	1.0	RMJ	Roots Medium Joint	120	M 3
	1.8	CL	Crack Longitudinal	175	S 2
Ш	2.0	RFJ(S01)	Roots Fine Joint	203	M 1
Camera Direction	9.7	JOM	Joint Offset Medium	263	S 3
	23.7	TFD	Tap Factory Defective	326	M 3
	25.7	TFC	Tap Factory Capped	350	NA
	25.7	RFJ(F01)	Roots Fine Joint	363	M 1
	34.2	MWLS	Miscellaneous Water Level Sag	401	S 2
	65.3	MWLS(S02)	Miscellaneous Water Level Sag	489	S 2
	72.6	JOM	Joint Offset Medium	528	S 3
	//74.2	TFD	Tap Factory Defective	558	M 3
	// / 74.7	CL	Crack Longitudinal	576	S 2
	87.3	MWLS(F02)	Miscellaneous Water Level Sag	638	S 2
	97.9	MWLS	Miscellaneous Water Level Sag	685	S 2
	105.9	DAE	Deposits Attached Encrustation	733	M 2
	111.1	DAE	Deposits Attached Encrustation	782	M 2
	116.1	В	Broken	835	S 4
	116.1	DAE	Deposits Attached Encrustation	869	M 2
	116.1	RFJ	Roots Fine Joint	901	M 1
	118.4	MWLS(S03)	Miscellaneous Water Level Sag	926	S 2
	125.2	TFD	Tap Factory Defective	976	M 3
	127.4	TFC	Tap Factory Capped	1009	NA
	128.0	MWLS(F03)	Miscellaneous Water Level Sag	1027	S 2
	133.1	MWLS(S04)	Miscellaneous Water Level Sag	1065	S 2
	135.5	JOMD	Joint Offset Medium Defective	1086	S 3
	// 138.0	RFJ	Roots Fine Joint	1115	M 1
	144.0	RFJ	Roots Fine Joint	1153	M 1
	146.3	MWLS(F04)	Miscellaneous Water Level Sag	1180	S 2
	146.9	AMH	Manhole	1206	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-005



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 1.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:


Value Percent: 45.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 1.8
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 2.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent:

Continuous Index: **S01**Within 8" of Joint: **YES**

Remarks:



Code: **JOM**

Description: Joint Offset Medium


Distance (ft): 9.7
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 23.7
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CAPPED. LARGE OFFSET FIRST JOINT

BACK. SOIL VISIIBLE



Code: TFC

Description: Tap Factory Capped

Distance (ft): 25.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 25.7
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 34.2
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 65.3
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:



Code: **JOM**

Description: Joint Offset Medium


Distance (ft): 72.6
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 74.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: LARGE OFFSET FIRST JOINT BACK.

SOIL VISIIBLE



Code: CL


Description: Crack Longitudinal

Distance (ft): 74.7
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



10/22/21

Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 87.3 Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 F02 Continuous Index: Within 8" of Joint: NO

Remarks:

0.00 ft/min

97.85 ft

Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 97.9 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 105.9 Structural Grade: 0 2 O&M Grade: Clock Start/From: 3 Clock To: 5


1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation**

YES

Distance (ft): 111.1 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:


YES



Code: Description: Broken

Distance (ft): 116.1 Structural Grade: 4 0 O&M Grade: Clock Start/From: 11 Clock To: 1 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES





Code: DAE

Description: **Deposits Attached Encrustation**


Distance (ft): 116.1 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



10/22/21

Code: RFJ

Description: **Roots Fine Joint**

Distance (ft): 116.1 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 9 Clock To: 3

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

0.00 ft/min

118.42 ft

YES

Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 118.4 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: S03 Within 8" of Joint: NO

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 125.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: LARGE OFFSET FIRST JOINT BACK.

SOIL VISIIBLE



Code: TFC

Description: Tap Factory Capped

Distance (ft): 127.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ROOTS IN THE JOINTS



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

128.0 Distance (ft): Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 F03 Continuous Index: Within 8" of Joint: NO

Remarks:



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 133.1 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S04** Within 8" of Joint: NO

Remarks:



Code: **JOMD**

Description: **Joint Offset Medium Defective**

Distance (ft): 135.5 Structural Grade: 3 0 O&M Grade:


Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



RFJ Code:

Description: **Roots Fine Joint**

Distance (ft): 138.0 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: **Roots Fine Joint**

Distance (ft): 144.0 Structural Grade: 0 O&M Grade: 1 2

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 146.3 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

5.000 Value Percent: Continuous Index: F04 Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 146.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: M-503-004

NO