

Profile/Photo Observation Report



Date:	04/12/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	186.6	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-503-010-009
Customer:		Clean Date:	01/01/1900	Shape:	C

Street:	ALLEY BETWEEN W 40TH AVE & W 3	Flow Control:	Not Controlled		
City:	Hobart, IN	Year Renewed:			
Location:	Other	Tape/Media #:			
Purpose:	Not Known	Dia/Height:	10"		
Use:	Sanitary	Material:	VCP		
Drain Area:	NA	Lining:			
Category:	NA				
Comment:					
Location Details:		Direction of Survey:	Downstream		
US MH:	M-503-009	DS MH:	M-503-010	Total Length Surveyed (ft):	5.8

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

Position	Code	Observation	Video (sec)	Grade
M-503-009				
.0	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
1.0	MMC	Material Change	35	NA
5.8	MSA	Abandoned Survey	56	NA

Code: **AMH**
Description: **Manhole**



Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-503-009**

Code: **MWL**
Description: **Water Level**



Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **20.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:

Code: **MMC**
Description: **Material Change**



Distance (ft): **1.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **pvc**



Code: **MSA**
Description: **Abandoned Survey**

Distance (ft): **5.8**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **debris under water**