## **Profile/Photo Observation Report**



Date: 04/12/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 186.6 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-503-010-009 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 40th ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-503-009 DS MH: M-503-010 Total Length Surveyed (ft): 5.8

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
M(503-)009				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
1.0	MMC	Material Change	35	NA
5.8	MSA	Abandoned Survey	56	NA
Camera Direction				

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-503-009	

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

20.000

NO

Code: MMC

Description: **Material Change** 



Distance (ft): 1.0 Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: pvc



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: debris under water