Profile/Photo Observation Report



Date: 04/10/2018 Weather: Coding: **PACP 6.0** Pipe Length (ft): 241.0 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Mark Ruby** PSR: P-503-014-012

Customer: Clean Date: 01/01/1900 Shape: C

Street: N VIRGINIA ST Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:


Location Details: Direction of Survey: **Downstream**

US MH: M-503-012 DS MH: M-503-014 Total Length Surveyed (ft): 76.8

O&M Index:	2.07	O&M Quick:	312A	O&M Rating:	31.00
Structural Index:	3.00	Structural Quick:	4132	Structural Rating:	12.00
Overall Index:	2.26	Overall Quick:	4133	Overall Rating:	43.00


Position	Code	Observation	Video (sec)	Grade
503-012				
.0	АМН	Manhole	10	NA
.0	MWL	Water Level	21	NA
5.4	DAE(S01)	Deposits Attached Encrustation	43	M 2
29.0	ID	Infil Dripper	102	M 3
29.2	TFC	Tap Factory Capped	114	NA
31.2	TFC	Tap Factory Capped	131	NA
49.1	TF	Tap Factory	179	NA
50.3	FL	Fracture Longitudinal	194	S 3
51.4	TF	Tap Factory	208	NA
55.3	CL	Crack Longitudinal	228	S 2
57.2	FM	Fracture Multiple	244	S 4
66.9	CM	Crack Multiple	275	S 3
76.8	DAE(F01)	Deposits Attached Encrustation	306	M 2
76.8	MSA	Abandoned Survey	317	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-503-012		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: DAE

Description: Deposits Attached Encrustation




Distance (ft): 5.4
Structural Grade: 0
O&M Grade: 2

Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES



Code: ID

Description: Infil Dripper


Distance (ft): 29.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 11
Clock To: 1
1st Value:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFC**

Description: Tap Factory Capped

Distance (ft): 29.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TFC**

Description: Tap Factory Capped

Distance (ft): 31.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 49.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: FL

Description: Fracture Longitudinal

Distance (ft): 50.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 1

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 51.4
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: CL

Description: Crack Longitudinal


Distance (ft): 55.3
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 57.2
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 11

Clock To: 3

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: CM

Description: Crack Multiple

Distance (ft): 66.9
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 10
Clock To: 3

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 76.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 76.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: DAE