Profile/Photo Observation Report



Date: 04/10/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 179.9 Owner: NA Pre Clean: **Not Known** P.O.#: P-503-023-022 Jen Costello PSR: Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN W 39TH PL & W 39 Flow Control: Not Controlled

City: Hobart, IN Year Renewed:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Other

Comment:

Location:

Location Details: Direction of Survey: **Downstream**


US MH: M-503-022 DS MH: M-503-023 Total Length Surveyed (ft): 10.7

3222 2.00 12.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 3222 12.00 Overall Index: Overall Quick: Overall Rating:

Tape/Media #:


	Code	Observation	Video (sec)	Grade
503-022				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	22	NA
1.0	RMJ	Roots Medium Joint	35	M 3
3.4	TFD	Tap Factory Defective	53	M 2
/3.4	RFL	Roots Fine Lateral	65	M 1
//3.7	RMJ(S01)	Roots Medium Joint	79	M 3
5.3	TFD	Tap Factory Defective	95	M 2
// 5.3	RFL	Roots Fine Lateral	106	M 1
10.7	RMJ(F01)	Roots Medium Joint	131	M 3
10.7	MSA	Abandoned Survey	142	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-022

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:


Within 8" of Joint:

Remarks:

NO

Code: RMJ

Description: Roots Medium Joint



Distance (ft): 1.0
Structural Grade: 0
O&M Grade: 3

Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 3.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: capped, rfl




Code: RFL

Description: Roots Fine Lateral

NO

Distance (ft): 3.4
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 1
Clock To: 3
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 3.7
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:

Code: **TFD**

Description: Tap Factory Defective



Distance (ft): 5.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: rfl, capped



Code: RFL

Description: Roots Fine Lateral

Distance (ft): 5.3
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 10
Clock To: 12
1st Value:
2nd Value:

Continuous Index:

Value Percent:

Within 8" of Joint:

Remarks:

NO



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 10.7
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 8

Clock To: 4

1st Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

2nd Value:



Code: MSA

Description: Abandoned Survey

Distance (ft): 10.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: rmj