
Date:	09/20/2021	Weather:		Coding:	<b>PACP 7.0</b>
Pipe Length (ft):	180.0	Owner:	City of Hobart	Pre Clea	in: Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-503-023-022
Customer:	City of Hobart	Clean Date:	09/04/2021	Shape:	С
Street:	West 39th Avenue		Flow Control:	Not Con	trolled
City:	Hobart, IN		Year Renewed:		
Location:	Alley		Tape/Media #:		
Purpose:	Routine Assessment		Dia/Height:	10"	
Use:	Sanitary Sewage Pipe	1	Material:	VCP	
Drain Area:			Lining:	None	
Category:	NA				
Comment:					
Location Details	:		Direction of Surv	vey: Downst	eam
US MH:	M-503-022	DS MH:	M-503-023	Total Length Surve	yed (ft): <b>30.7</b>
0&M Index:	2.15	O&M Quick:	413	<sup>3</sup> O&M Ratin	g: 28.00
tructural Index:	2.50	Structural Qu	uck: 312		
Overall Index:	2.20		413		

	Position	Code	Observation	Video (sec)	Grade
M-50	022				
	.0	AMH	Manhole	1	NA
- H	.0	MWL	Miscellaneous Water Level	68	NA
- 11	.0	DSF(S01)	Deposits Settled Fine	78	M 2
- 11	1.9	RFJ	Roots Fine Joint	113	M 1
		TFC	Tap Factory Capped	138	NA
	4.0	RFJ	Roots Fine Joint	195	M 1
- 11	4.0	CL	Crack Longitudinal	212	S 2
- 11	5.6	TFC	Tap Factory Capped	239	NA
- 11	6.3	RMJ(S02)	Roots Medium Joint	294	M 3
5	14.1	СМ	Crack Multiple	364	S 3
ecti	14.1	RFJ	Roots Fine Joint	410	M 1
10 L	14.1	RMJ	Roots Medium Joint	438	M 3
Camera Direction	16.4	MMC	Miscellaneous Material Change	532	NA
Car	16.4	RMJ(F02)	Roots Medium Joint	544	M 3
	28.4	MMC	Miscellaneous Material Change	632	NA
	30.0	RBJ	Roots Ball Joint	674	M 4
<b>↓</b>	30.7	DSF(F01)	Deposits Settled Fine	695	M 2
- 11	30.7	MSA	Miscellaneous Survey Abandoned	706	NA
м <del>.</del> 50	<b>3-023</b>				



Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-022

Thursday, December 30, 2021




Code:	MWL
Description:	Miscellaneous Water Level
/0	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	DSF Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value:	.0 0 2 5 7
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	5.000 S01 YES




Code:	RFJ
Description:	<b>Roots Fine Joint</b>
Distance (ft):	1.9
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	1
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TFC Tap Factory Capped
Distance (ft):	3.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	ROOTS GROWING AROUND THE CAP



Code:	RFJ
Description:	<b>Roots Fine Joint</b>
Distance (ft):	4.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	9
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	CL Crack Longitudinal
Distance (ft):	4.0
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TFC
Description:	Tap Factory Capped
Distance (ft):	5.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	ROOTS GROWING AROUND THE CAP



Code:	RMJ
Description:	Roots Medium Joint
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	6.3 0 3 9 2 5.000 \$02 YES



Code: Description:	CM Crack Multiple
Distance (ft):	14.1
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	RFJ Roots Fine Joint
Distance (ft):	14.1
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: Description:	RMJ Roots Medium Joint
Distance (ft): Structural Grade: O&M Grade: Clock Start/From:	14.1 0 3 12
Clock To: 1st Value: 2nd Value:	4
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	20.000 YES




Code: Description:	MMC Miscellaneous Material Change
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value:	16.4 0 0
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	NO VCP TO PVC




Code:	RMJ
Description:	<b>Roots Medium Joint</b>
Dictance (ft):	16.4
Distance (ft):	10.4
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	9
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	




Code: Description:	MMC Miscellaneous Material Change
Distance (ft):	28.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	ΡVC ΤΟ VCP



Code:	RBJ
Description:	<b>Roots Ball Joint</b>
Distance (ft):	30.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	7
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	85.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Distance (ft):30.7Structural Grade:0O&M Grade:2Clock Start/From:5Clock To:71st Value:2nd Value:Value Percent:5.000Continuous Index:F01Within 8" of Joint:YESRemarks:	



Code:	MSA
Description:	Miscellaneous Survey Abandoned
Distance (ft):	30.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	CAMERA CANT MAKE IT PAST ROOTS