Profile/Photo Observation Report



Date: 09/20/2021 Weather: **PACP 7.0** Coding: Pipe Length (ft): Owner: **City of Hobart** Pre Clean: **Light Cleaning** 1.9 P.O.#: YES502259 S. Bucklin PSR: P-503-0SL-026 Surveyor: Customer: **City of Hobart** Clean Date: 08/28/2021 Shape:

Street: West 41st Avenue Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Local rural streets with light traffic, t Tape/Media #:

Purpose: Routine Assessment Dia/Height: 6"
Use: Sanitary Sewage Pipe Material: VCP

Drain Area: Lining: None

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-503-026 DS MH: M-503-026.1 Total Length Surveyed (ft): 1.8

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:


	Position	Code	Observation	Video (sec)	Grade
M-503-02	26.1				
\mathcal{L}	0. 📈	AMH	Manhole	1	NA
- 11	\.0	MWL	Miscellaneous Water Level	10	NA
- 11	1.5	MGO	Miscellaneous General Observation	21	NA
- 11	1.5	DAE	Deposits Attached Encrustation	70	M 2
- 11	1.8	MSA	Miscellaneous Survey Abandoned	121	NA
Camera Direction					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-026.1

AMH



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: MGO

Description: Miscellaneous General Observation


Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: DROP INTO THE MANHOLE. HAD TO

START IN THE PIPE.



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 1.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To: 10

1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Miscellaneous Survey Abandoned

Distance (ft): 1.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: CAMERA CANT MAKE IT PAST

ENCRUSTATIOIN