
Profile/Ph	oto Observatio	n Report			RedZon
Date:	04/09/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft P.O.#:	:): <b>161.9</b>	Owner:	NA Mark Buby	Pre Clean: PSR:	Not Known P-503-031-032
Customer:		Surveyor: Clean Date:	Mark Ruby 01/01/1900	Shape:	P-505-051-052 C
Street:	N DELAWARE ST	& W 41ST AVE	Flow Control:	Not Control	ed
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ls:		Direction of Sur	rvey: Downstrean	n
US MH:	M-503-032	DS MH:	M-503-031	Total Length Surveyed	(ft): <b>157.7</b>
0&M Index:	2.00	O&M Quick:	24	00 O&M Rating:	8.00
tructural Index:	4.00	Structural Q	uick: 4D	00 Structural Ratir	ng: <b>112.00</b>
Overall Index:	3.75	Overall Quic	k <sup>.</sup> 4D	24 Overall Rating:	120.00

NA NA 5 4 5 4 M 2
NA 5 4 5 4
54 54
54
<u>v1 2</u>
VI 2
54
54
54
54
VI 2
VI 2
M 2
54
NA




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-032

M(503-031



Code: MWL Description: Water Level

.0
0
0
10.000
NO




Code: Description:	FM Fracture Multiple
Distance (ft):	4.7
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:FMDescription:Fracture Multiple

Distance (ft):	10.5
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TBI Tap Break-in Intruding
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	53.2 0 2 10 4.000 1.000




Code:	FM
Description:	Fracture Multiple

Distance (ft):	53.2
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	



Code: Description:	FM Fracture Multiple
Distance (ft):	57.5
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:FMDescription:Fracture Multiple

Distance (ft):	63.5
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	FM Fracture Multiple
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	75.2 4 0 7 5 5 S02 YES



Code: **TBI** Description: **Tap B** 

Tap Break-in Intruding

Distance (ft):	97.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	
1st Value:	4.000
2nd Value:	1.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	and the	111
The Miles		

Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	154.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	IW
Description:	Infil Weeper

Distance (ft):	154.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	FM
Description:	Fracture Multiple
	456.4
Distance (ft):	156.1
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	



Code: Description:	AMH Manhole
Distance (ft): Structural Grade:	157.7 0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

NO M-503-031