
Profile/Ph	oto Observation I	Report				RedZon
Date:	09/29/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)	: <b>207.9</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Ho	onu	PSR:	P-503-036-037
Customer:		Clean Date:	01/01/190	00	Shape:	С
Street:	W 40TH AVE		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Light Highway		Tape/Media	a #:		
Purpose:	<b>Routine Assessment</b>	:	Dia/Height:		8"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	s:		Direction of	Survey:	Upstream	
US MH:	M-503-037	DS MH:	M-503-036	т	otal Length Surveyed (ft):	5.0
0&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
tructural Index:		 Structural Qu	uick:	0000	 Structural Rating:	0.00
Overall Index:	0.00	Overall Quicl	<:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-036



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	5.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	ROOT INFILTRATION