Profile/Photo Observation Report



Date: 04/07/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 204.7 Owner: NA Pre Clean: **Not Known** P.O.#: **Mark Ruby** PSR: P-503-037-038 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: canender st Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:


Location Details: Direction of Survey: **Downstream**

US MH: M-503-038 DS MH: M-503-037 Total Length Surveyed (ft): 208.1

2.00 2600 12.00 O&M Index: O&M Quick: O&M Rating: 3.67 11.00 Structural Quick: Structural Rating: Structural Index: 2.56 23.00 Overall Index: Overall Quick: Overall Rating:


.0 .0 .0 3.8 10.1 74.4		Manhole Water Level Fracture Multiple	10 21 40	NA NA
.0 3.8 10. 12. 74.	MWL FM 7 TF	Water Level Fracture Multiple	21	
3.8 10. 12. 74.	FM 7 TF	Fracture Multiple		NA
10. 12. 74.	7 TF	<u> </u>	40	
74.			40	S 4
74.4	7 TC	Tap Factory	66	NA
	, 15	Tap Factory	83	NA
	4 MMC	Material Change	218	NA
/75.8	3 TF	Tap Factory	233	NA
// 77.:	B DAGS	Deposits Attached Grease	248	M 2
77.8	8 MMC	Material Change	260	NA
83.9	9 FM	Fracture Multiple	283	S 4
112	.2 MMC	Material Change	351	NA
/115	.6 MMC	Material Change	370	NA
// 129	.8 FS	Fracture Spiral	409	S 3
/ 145	.1 IW	Infil Weeper	452	M 2
//145	.1 DAZ	Deposits Attached Other	463	M 2
// 160	.6 IW	Infil Weeper	505	M 2
// 186	.3 IW	Infil Weeper	568	M 2
//201	.3 IW	Infil Weeper	610	M 2
/ /208	.1 AMH	Manhole	635	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-503-038		

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO




Code: FM

Description: Fracture Multiple

Distance (ft): 3.8
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:



Code: **TF**

Description: Tap Factory


Distance (ft): 10.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 12.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MMC

Description: Material Change

Distance (ft): 74.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Description:

Within 8" of Joint: NO Remarks: PVC

Code: **TF**

Tap Factory

4.000

Distance (ft): **75.8**Structural Grade: **0**O&M Grade: **0**


O&M Grade: 0
Clock Start/From: 10


1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Clock To:





Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 77.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MMC

Description: Material Change

Distance (ft): 77.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: VCP



Code:

Description: Fracture Multiple

FΜ

Distance (ft): 83.9
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 8

Clock To: 4

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

1st Value:



Code: MMC

Description: Material Change

Distance (ft): 112.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Code: MMC

Description: Material Change

Distance (ft): 115.6
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO Remarks: VCP




Code: FS

Description: Fracture Spiral

Distance (ft): 129.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 8
Clock To: 9
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: IW

Description: Infil Weeper


Distance (ft): 145.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAZ

Description: Deposits Attached Other


Distance (ft): 145.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES



Code: IW

Description: Infil Weeper

Distance (ft): 160.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IW

Description: Infil Weeper

Distance (ft): 186.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: IW

Description: Infil Weeper


Distance (ft): 201.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: AMH
Description: Manhole

Distance (ft): 208.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-037