Profile/Photo Observation Report



Date: 04/07/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 478.8 Owner: NA Pre Clean: **Not Known** P.O.#: **Mark Ruby** PSR: P-503-042-041 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: PENNSYLVANIA ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-503-041 DS MH: M-503-042 Total Length Surveyed (ft): 301.4

1.33 2112 4.00 O&M Index: O&M Quick: O&M Rating: 3.35 67.00 Structural Index: Structural Quick: Structural Rating: 3.09 71.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
л (50	3-041				
	0.	AMH	Manhole	10	NA
-11	0.	MWL	Water Level	21	NA
ш	5.7	FM	Fracture Multiple	44	S 4
ш	47.8	FL	Fracture Longitudinal	140	S 3
ш	47.8	FL	Fracture Longitudinal	151	S 3
H	51.8	FM	Fracture Multiple	171	S 4
н	58.9	MMC	Material Change	197	NA
Н	67.0	MMC	Material Change	224	NA
	67.4	FL	Fracture Longitudinal	236	S 3
	\\\ 69.6	FM	Fracture Multiple	253	S 4
	71.2	DAR	Deposits Attached Ragging	267	M 2
	75.0	TF	Tap Factory	287	NA
	117.0	FM	Fracture Multiple	382	S 4
	127.2	FM	Fracture Multiple	415	S 4
н	138.2	FM	Fracture Multiple	449	S 4
н	143.7	RFJ	Roots Fine Joint	472	M 1
 	157.6	FM(S01)	Fracture Multiple	511	S 4
Ш	176.3	FM(F01)	Fracture Multiple	560	S 4
ш	195.3	TF	Tap Factory	610	NA
	/ 200.8	RFJ	Roots Fine Joint	633	M 1
ш	200.8	CM	Crack Multiple	644	S 3
ш	212.3	TF	Tap Factory	679	NA
	//_214.3	MMC	Material Change	695	NA
ш	215.8	TF	Tap Factory	710	NA
E	218.7	MMC	Material Change	728	NA
ш	248.7	CL	Crack Longitudinal	799	S 2
ш	262.2	CL	Crack Longitudinal	838	S 2
ш	//262.6	CM	Crack Multiple	851	S 3
	271.0	CL	Crack Longitudinal	879	S 2
н	274.4	TFC	Tap Factory Capped	898	NA
	_/	TF	Tap Factory	923	NA
	293.2	CL	Crack Longitudinal	959	S 2
	294.1	FM	Fracture Multiple	973	S 4
	301.4	AMH	Manhole	999	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-041



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0


Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Description: Fracture Multiple

Distance (ft): 5.7
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 7


Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: FL

Description: Fracture Longitudinal




Distance (ft): 47.8
Structural Grade: 3
O&M Grade: 0

O&M Grade: 0
Clock Start/From: 9

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Clock To:




Code: FL

Description: Fracture Longitudinal

Distance (ft): 47.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 1

Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: **FM**

Description: Fracture Multiple

Distance (ft): 51.8
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:



Code: MMC

Description: Material Change


Distance (ft): 58.9
Structural Grade: 0

O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO Remarks: PVC



Code: MMC


Description: Material Change

Distance (ft): 67.0
Structural Grade: 0

O&M Grade: **0**Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: VCP




Code: FL

Description: Fracture Longitudinal

Distance (ft): 67.4
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 11

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: **FM**

Description: Fracture Multiple

Distance (ft): 69.6
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 7

Clock To: 5


1st Value:

2nd Value:

Value Percent:

Remarks:

Continuous Index: Within 8" of Joint:



Code: DAR

Description: Deposits Attached Ragging

Distance (ft): 71.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10

Clock To: 1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**


Description: Tap Factory

Distance (ft): 75.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:




Description: Fracture Multiple

Distance (ft): 117.0
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:




Code: FM

Description: Fracture Multiple

Distance (ft): 127.2
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Continuous Index: Within 8" of Joint:

Value Percent:



Description: Fracture Multiple


Distance (ft): 138.2
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: RFJ

Description: Roots Fine Joint



Distance (ft): 143.7
Structural Grade: 0
O&M Grade: 1


Clock Start/From: 12
Clock To:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

1st Value:



Description: Fracture Multiple

S01

F01

Distance (ft): 157.6
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 7

Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

Code: FM
Description: Fracture Multiple

Distance (ft): 176.3
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

.....





Code: **TF**

Description: Tap Factory

Distance (ft): 195.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10


Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:


Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 200.8 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES



Code: CM

Description: Crack Multiple

Distance (ft): 200.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 212.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MMC

Description: Material Change

Distance (ft): 214.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: pvc



Code: **TF**

Description: Tap Factory

Distance (ft): 215.8
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MMC

Description: Material Change

Distance (ft): 218.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: VCP



Code: CL

Description: Crack Longitudinal

Distance (ft): 248.7
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 4
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 262.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 8

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:


Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 262.6 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 12 3 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES




Code: CL

Description: Crack Longitudinal

Distance (ft): 271.0
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 10

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 274.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 280.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 293.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 4

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Fracture Multiple

Distance (ft): 294.1
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 301.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-042