Profile/Photo Observation Report



Date: 04/10/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 290.6 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-503-051-052

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 40th ave Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: CP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Upstream**

US MH: M-503-052 DS MH: M-503-051 Total Length Surveyed (ft): 7.2

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 3.00 3100 3.00 Structural Quick: Structural Rating: Structural Index: 3121 2.50 5.00 Overall Index: Overall Quick: Overall Rating:

	ion Code	Observation	Video (sec)	Grade
M(503-051				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
0.\\	SAP	Surface Aggregate Projecting	32	S 3
\.0	DAGS	Deposits Attached Grease	44	M 2
7.2	MSA	Abandoned Survey	69	NA
Camera Direction				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-051

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

40.000

NO



Code: SAP

Description: **Surface Aggregate Projecting**

Distance (ft): .0 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 8 Clock To: 1st Value: 2nd Value:

Continuous Index: Within 8" of Joint:

Value Percent:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 7.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: debris under water