Date:	04/14/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	203.0	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-503-053-054
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	W 40th ave		Flow Control:	Not Controlled	I
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details	5:		Direction of Surv	vey: Downstream	
US MH:	M-503-053	DS MH:	M-503-054	Total Length Surveyed (ft	): <b>85.8</b>
D&M Index:	2.17	O&M Quick:	413	2 O&M Rating:	52.00
Structural Index:	0.00	Structural Qu			0.00
Overall Index:	2.17	Overall Quic	442		52.00

	Position	Code	Observation	Video (sec)	Grade
M(503-0	)53				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	\	MGO	General Observation	39	NA
	9.3	IW(S01)	Infil Weeper	65	M 2
	14.3	DAE	Deposits Attached Encrustation	87	M 2
	45.2	ID	Infil Dripper	160	M 3
	55.5	ID	Infil Dripper	193	M 3
	60.5	DAE(S02)	Deposits Attached Encrustation	215	M 2
	85.8	DAE(F02)	Deposits Attached Encrustation	279	M 2
5	85.8	IW(F01)	Infil Weeper	291	M 2
ecti	85.8	MSA	Abandoned Survey	302	NA
ā	85.8	MCU	Camera Underwater	313	M 4
Camera Direction					
M(503)0	)54				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-053




Code: Description:

MWL

Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 100.000 Continuous Index: Within 8" of Joint: NO Remarks:




	Code:	MGO	
Description:		General Observation	
	Distance (ft):	1.9	
	Structural Grade:	0	
	O&M Grade:	0	
	Clock Start/From:		
	Clock To:		
	1st Value:		
	2nd Value:		

NO

**REAR CAMERA** 


Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code:	IW
Description:	Infil Weeper
Distance (ft):	9.3

Distance (ft):	9.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	YES
Remarks:	




Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	14.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	ID
Description:	Infil Dripper

45.2
0
3
12
YES



ID Infil Dripper
55.5
0
3
12
YES



Code:DAEDescription:Deposits Attached Encrustation

Distance (ft):	60.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S02
Within 8" of Joint:	YES
Remarks:	

Code:

Remarks:



Description:	Deposits Attached Encrustation
Distance (ft):	85.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F02
Within 8" of Joint:	YES

DAE




Code:	IW
Description:	Infil Weeper

Distance (ft):	85.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	



Code:	MSA	
Description:	Abandoned Survey	
Distance (ft):	85.8	
Structural Grade:	0	
	•	

Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	MCU



Code: Description: MCU Camera Underwater

Distance (ft):	85.8
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	