## **Profile/Photo Observation Report**



Date: 04/15/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 175.1 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-503-069-068 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 40th ave Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location:OtherTape/Media #:Purpose:Not KnownDia/Height:8"

Use: Sanitary Material: VCP

Drain Area: NA Lining: Category: NA


Comment:

Location Details: Direction of Survey: Downstream

US MH: **M-503-068** DS MH: **M-503-069** Total Length Surveyed (ft): **119.8** 

322B 2.10 42.00 O&M Index: O&M Quick: O&M Rating: 1.00 1100 1.00 Structural Quick: Structural Rating: Structural Index: 2.05 322B 43.00 Overall Quick: Overall Rating: Overall Index:

Position	n Code	Observation	Video (sec)	Grade
503-068				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
7.8	DAE	Deposits Attached Encrustation	48	M 2
13.1	DAE	Deposits Attached Encrustation	70	M 2
22.8	DAE(S01)	Deposits Attached Encrustation	100	M 2
23.2	ID	Infil Dripper	113	M 3
28.0	ID	Infil Dripper	134	M 3
33.0	DAE(F01)	Deposits Attached Encrustation	156	M 2
47.6	DAE	Deposits Attached Encrustation	196	M 2
47.7	IW	Infil Weeper	207	M 2
52.7	IW	Infil Weeper	229	M 2
52.9	DAE	Deposits Attached Encrustation	241	M 2
64.6	DAE	Deposits Attached Encrustation	275	M 2
/71.2	TFA	Tap Factory Active	300	NA
//71.5	DAE	Deposits Attached Encrustation	313	M 2
7//76.1	DAE	Deposits Attached Encrustation	333	M 2
81.3	DAE	Deposits Attached Encrustation	355	M 2
//81.4	IW	Infil Weeper	367	M 2
91.0	DAE	Deposits Attached Encrustation	397	M 2
/91.5	IW	Infil Weeper	410	M 2
93.3	TF	Tap Factory	425	NA
93.3	DAE	Deposits Attached Encrustation	437	M 2
93.7	IW	Infil Weeper	449	M 2
98.5	CC	Crack Circumferential	471	S 1
98.5	IS	Infil Stain	482	NA
103.7	IW	Infil Weeper	504	M 2
113.8	MWL	Water Level	535	NA
119.8	MSA	Abandoned Survey	559	NA



Code: AMH
Description: Manhole


Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-068



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Description: Deposits Attached Encrustation

Distance (ft): 7.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 13.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Description: Deposits Attached Encrustation

Distance (ft): 22.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: ID

Description: Infil Dripper


Distance (ft): 23.2
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12
Clock To:
1st Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: ID

Description: Infil Dripper


Distance (ft): 28.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 11
Clock To: 1
1st Value:
2nd Value:

Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 33.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

YES

5.000

F01

Description: **Deposits Attached Encrustation** 

Distance (ft): 47.6 Structural Grade: 0 2 O&M Grade: Clock Start/From: 7 Clock To: 5

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IW

Description: Infil Weeper

Distance (ft): 47.7 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: IW

Description: Infil Weeper

Distance (ft): 52.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8


Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

YES

Distance (ft): 52.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:



Description: Deposits Attached Encrustation

Distance (ft): 64.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

YES

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 71.2
Structural Grade: 0


O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Deposits Attached Encrustation

Distance (ft): 71.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10
Clock To: 4
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

YES

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 76.1
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 12

1st Value:

2nd Value: Value Percent:

e Percent: **5.000** 

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Description: **Deposits Attached Encrustation** 

Distance (ft): 81.3 Structural Grade: 0 2 O&M Grade: Clock Start/From: 7 Clock To: 5 1st Value:

2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: IW

Description: Infil Weeper

Distance (ft): 81.4 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

YES



Description: Deposits Attached Encrustation

Distance (ft): 91.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint:

Remarks:

YES

YES



Code: IW

Description: Infil Weeper

Distance (ft): 91.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value: 2
2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: Remarks:

Tuesday, December 8, 2020



Code: **TF** 

Description: Tap Factory

Distance (ft): 93.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: DAE

Description: Deposits Attached Encrustation

4.000




Distance (ft): 93.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES



Code: IW

Description: Infil Weeper


Distance (ft): 93.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: CC

Description: Crack Circumferential

Distance (ft): 98.5
Structural Grade: 1
O&M Grade: 0
Clock Start/From: 3
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: IS

Description: Infil Stain

Distance (ft): 98.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3
Clock To: 5
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IW

Description: Infil Weeper

Distance (ft): 103.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 12
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: MWL

Description: Water Level

Distance (ft): 113.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 119.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: CAMERA STOPPED