Profile/Photo Observation Report



Date: 04/14/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 176.2 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-503-071-063

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 38TH AVE Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-503-071 DS MH: M-503-063 Total Length Surveyed (ft): 307.9

362U 2.05 240.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.05 **362U** 240.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
503-07	1				
otan	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	3.7	IS	Infil Stain	40	NA
	\\8.8	DAE	Deposits Attached Encrustation	62	M 2
-M	8.8	IW	Infil Weeper	73	M 2
	19.0	ID	Infil Dripper	105	M 3
	19.0	DAE	Deposits Attached Encrustation	116	M 2
	35.1	DAE(S01)	Deposits Attached Encrustation	159	M 2
	35.1	IW(S02)	Infil Weeper	170	M 2
	50.4	ID	Infil Dripper	212	M 3
	123.8	ID	Infil Dripper	370	M 3
	259.9	ID	Infil Dripper	654	M 3
	259.9	DAE	Deposits Attached Encrustation	665	M 3
	266.1	TFD	Tap Factory Defective	689	M 2
	266.1	DAE	Deposits Attached Encrustation	700	M 2
	277.8	ID	Infil Dripper	736	M 3
	298.6	IW(F02)	Infil Weeper	789	M 2
	298.6	DAE(F01)	Deposits Attached Encrustation	800	M 2
	298.6	MMC	Material Change	811	NA
	300.6	TFA	Tap Factory Active	827	NA
	303.2	MMC	Material Change	844	NA
 //	307.9	MSA	Abandoned Survey	864	NA
	/				

Code:

Description:



D: 1 (6)	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-071

AMH

Manhole



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

Code: IS Description: **Infil Stain**



Distance (ft): 3.7


Structural Grade: 0 O&M Grade: 0 Clock Start/From: 8 Clock To: 11

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 8.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 11

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES




Code: IW

Description: Infil Weeper

Distance (ft): 8.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Description: Infil Dripper


Distance (ft): 19.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 19.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 4
1st Value:
2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 35.1
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:


Code: IW

Description: Infil Weeper



Distance (ft): 35.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index: 502

Within 8" of Joint: YES



Description: Infil Dripper

Distance (ft): 50.4
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 11


Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES

YES




Code: ID

Description: Infil Dripper

Distance (ft): 123.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1
Clock To:
1st Value:
2nd Value:
Value Percent:

Within 8" of Joint:

Continuous Index:



Description: Infil Dripper


Distance (ft): 259.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 11

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation


Distance (ft): 259.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 11
1st Value:

2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: YES



Code: **TFD**

Description: Tap Factory Defective


Distance (ft): 266.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: DAE



Code: DAE

Description: Deposits Attached Encrustation


Distance (ft): 266.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Description: Infil Dripper

Distance (ft): 277.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES

YES



Code: IW

Description: Infil Weeper

Distance (ft): 298.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value: 2

2nd Value: Value Percent: Continuous Index: F02

Remarks:

Within 8" of Joint:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 298.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

Code: MMC

Description: Material Change




Distance (ft): 298.6 Structural Grade: 0

O&M Grade: **0**

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: pvc



Code: TFA

Description: Tap Factory Active

Distance (ft): 300.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2


Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC

Description: Material Change


Distance (ft): 303.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: dae



Code: MSA

Description: Abandoned Survey

Distance (ft): 307.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: debris under water

NO