Profile/Photo Observation Report



Date: 04/12/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 225.6 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-503-080-079 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 40th ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-503-079 DS MH: M-503-080 Total Length Surveyed (ft): 224.7

2.04 5132 188.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.04 5132 188.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
503-	079				
	0.	АМН	Manhole	10	NA
ш	0.	MWL	Water Level	22	NA
		DAGS(S01)	Deposits Attached Grease	33	M 2
	3.1	TF	Tap Factory	51	NA
Н	ן /\\ 18.2	IW	Infil Weeper	93	M 2
Н	18.2	MWL	Water Level	104	NA
	19.2	TF	Tap Factory	118	NA
ш	29.6	DAE	Deposits Attached Encrustation	150	M 2
	35.7	DAE	Deposits Attached Encrustation	174	M 3
ш	36.4	TFD	Tap Factory Defective	187	M 2
ш	41.3	DAE	Deposits Attached Encrustation	209	M 2
ш	41.3	DAGS(F01)	Deposits Attached Grease	220	M 2
ш	46.4	DAE(S02)	Deposits Attached Encrustation	242	M 2
Н	46.4	IW(S03)	Infil Weeper	253	M 2
н	57.8	TFD	Tap Factory Defective	288	M 2
н	57.8	RFL	Roots Fine Lateral	299	M 1
Н	¬ ∭ 94.2	TBA	Tap Break-in Active	384	NA
ш	94.2	DAE	Deposits Attached Encrustation	395	M 2
Н	ر \\ <u>98.9</u>	ID	Infil Dripper	417	M 3
н	115.4	TFC	Tap Factory Capped	461	NA
н	128.1	ТВ	Tap Break-in	499	NA
П	147.0	TFA	Tap Factory Active	550	NA
н	147.0	DAGS	Deposits Attached Grease	561	M 2
Н	148.8	TFD	Tap Factory Defective	577	M 2
н	148.8	DAE	Deposits Attached Encrustation	588	M 5
н	162.6	DAGS	Deposits Attached Grease	627	M 2
ш	163.3	TBA	Tap Break-in Active	641	NA
ш	163.9	DAGS	Deposits Attached Grease	654	M 2
ш	209.4	TFC	Tap Factory Capped	757	NA
	222.8	IW(F03)	Infil Weeper	795	M 2
	222.8	DAE(F02)	Deposits Attached Encrustation	806	M 2
	224.7	AMH	Manhole	822	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-079



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:


2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:

Code: **TF**

Description: Tap Factory




Distance (ft): 3.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: IW

Description: Infil Weeper


Distance (ft): 18.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 4
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MWL

Description: Water Level

Distance (ft): 18.2
Structural Grade: 0
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: **TF**

Description: Tap Factory

Distance (ft): 19.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Deposits Attached Encrustation




Distance (ft): 29.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value: Value Percent:

/alue Percent: 10.000

Continuous Index:

Within 8" of Joint: YES



Description: Deposits Attached Encrustation

Distance (ft): 35.7
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 36.4
Structural Grade: 0

O&M Grade: 2


Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: DAE



Description: Deposits Attached Encrustation

Distance (ft): 41.3
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 12

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAGS


Description: Deposits Attached Grease

Distance (ft): 41.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

2nd Value:



Description: Deposits Attached Encrustation

Distance (ft): 46.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value:


2nd Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: YES

Remarks:

Code: IW

Description: Infil Weeper



Distance (ft): 46.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Continuous Index: **S03**Within 8" of Joint: **YES**

Remarks:

Value Percent:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 57.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: ROOTS



Code: RFL

Description: Roots Fine Lateral


Distance (ft): 57.8
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO



Code: TBA

Description: Tap Break-in Active

Distance (ft): 94.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: DAE



Code: DAE

Description: Deposits Attached Encrustation


Distance (ft): 94.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Code: **ID**

Description: Infil Dripper

Distance (ft): 98.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFC**


Description: Tap Factory Capped

Distance (ft): 115.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TB

Description: Tap Break-in


Distance (ft): 128.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 147.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2


Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Tuesday, December 8, 2020



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 147.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TFD**

Description: Tap Factory Defective


Distance (ft): 148.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: AE



Description: Deposits Attached Encrustation

Distance (ft): 148.8
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 6
Clock To: 11

1st Value: 2nd Value:


Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAGS

Description: Deposits Attached Grease


Distance (ft): 162.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 12
1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Code: TBA

Description: **Tap Break-in Active**


Distance (ft): 163.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 12

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: **Deposits Attached Grease**

Distance (ft): 163.9 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 5 Clock To: 1st Value:


Value Percent: Continuous Index:

10.000

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: **TFC**

Description: Tap Factory Capped

Distance (ft): 209.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: IW

Description: Infil Weeper

Distance (ft): 222.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index: F03

Within 8" of Joint: YES



Description: Deposits Attached Encrustation

Distance (ft): 222.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 10.000
Continuous Index: F02
Within 8" of Joint: YES

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 224.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-503-080