
Profile/Ph	oto Observatio	n Report			RedZo
Date:	09/29/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	t): 547.5	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Justin Gonzale	es PSR:	P-503-090-089
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	40th. Ave.		Flow Control:	Not Controlled	I
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ils:		Direction of Sur	vey: Downstream	
US MH:	M-503-089	DS MH:	M-503-090	Total Length Surveyed (ft): 365.8
D&M Index:	3.00	O&M Quick:	412	21 O&M Rating:	6.00
Structural Index	. 0.00	Structural Qu	uick: 000	00 Structural Rating:	0.00
Overall Index:	3.00	Overall Quicl	. 412		6.00

	Positic	on Code	Observation	Video (sec)	Grade
M-50	03-089				
	.0	AMH	Manhole	10	NA
- E	.0	MWL	Water Level	21	NA
	10.9	MCU	Camera Underwater	54	M 4
	16.9	TFA	Tap Factory Active	78	NA
	22.9	MGO	General Observation	102	NA
	26.0	TFA	Tap Factory Active	123	NA
	106.5	TF	Tap Factory	297	NA
Ē	108.9	TF	Tap Factory	315	NA
	200.0	DAGS	Deposits Attached Grease	509	M 2
5	215.3	TF	Tap Factory	551	NA
ecti	231.6	TF	Tap Factory	597	NA
<u>p</u>	///312.4	TF	Tap Factory	770	NA
Camera Direction	315.4	TF	Tap Factory	788	NA
E	365.8	MSA	Abandoned Survey	902	NA



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-503-089

M(503)090



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 15.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code:	MCU
Description:	Camera Underwater


Distance (ft): 10.9 Structural Grade: 0 O&M Grade: 4 Clock Start/From: Clock To: 1 1st Value: 2 nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: NO

Tuesday, December 8, 2020




Code:TFADescription:Tap Factory Active

Distance (ft):	16.9
Distance (It).	10.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	MGO
Description:	General Observation
Distance (ft):	22.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	DEPOSITS ON FRONT LENS



Code:TFADescription:Tap Factory Active

Distance (ft):	26.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	106.5 0 0 9 6.000
Continuous Index: Within 8" of Joint: Remarks:	



Code: TF Description: Tap Factory

Distance (ft):	108.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	200.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	215.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	231.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TF
Description:	Tap Factory

Distance (ft):	312.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	315.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description: MSA Abandoned Survey

Distance (ft):	365.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	ROBOT

NO ROBOT HAS STOPPED