Profile/Photo Observation Report



Date: 04/24/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 165.8 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Jen Costello PSR: P-504-011-010

Customer: Clean Date: 01/01/1900 Shape: C

Street: W HOME AVE Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"

Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Location Details: Direction of Survey: Upstream

US MH: M-504-010 DS MH: M-504-011 Total Length Surveyed (ft): 6.6

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2100 2.00 Overall Index: Overall Rating: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
M(504-)01:	1				
	.0	АМН	Manhole	10	NA
	.0	MWL	Water Level	22	NA
,	4.1	DAE	Deposits Attached Encrustation	41	M 2
	6.6	MSA	Abandoned Survey	58	NA
Camera Direction M(-504-010	0				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value: Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-011

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value:

2nd Value:

Value Percent: 5

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: DAE

Description: Deposits Attached Encrustation


Distance (ft): 4.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 6.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: debris under water