## **Profile/Photo Observation Report**



Profile/Photo Observation Report								
Date: Pipe Length (f		Weather: Owner:	City of Hoba		Pre Clean:	PACP 6.0 No Pre-Cleaning		
P.O.#:	48-1	Surveyor:	M. Pielacha		_	M-504-028-M-504-027		
Customer:	City of Hobart	Clean Date:			Shape:	C		
Street:	<b>Cleveland Avenue</b>		Flow Control:		Not Controlled			
City:	Hobart, IN		Year Renewe	d:				
Location:	<b>Light Highway</b>		Tape/Media	<b>#</b> :	<b>DEP 48</b>			
Purpose:	Routine Assessment	t	Dia/Height:		18"			
Use:	Sanitary		Material:		VCP			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Deta	ils:		Direction of S	urvey:	Downstream			
US MH:	M-504-028	DS MH:	M-504-027		Total Length Surveyed (ft):	319.2		
O&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00		
Structural Index	0.00	Structural Q		0000	Structural Rating:	0.00		
Overall Index:	0.00	— Overall Quic	k:	0000	Overall Rating:	0.00		

Thursday, May 4, 2023 1

Position	Code	Observation	Video (sec)	Grade
504-028				
0.	AMH	Manhole	0	NA
0.	MWL	Water Level	5	NA
319.2	АМН	Manhole	348	NA
504)027				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-504-028		

 $\mathsf{AMH}$ 

Thursday, May 4, 2023 2



Code: MWL Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

10.000



Code: AMH Description: Manhole

Distance (ft): 319.2 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-027

3 Thursday, May 4, 2023