## **Profile/Photo Observation Report**



Date: 11/02/2021 Weather: **PACP 7.0** Coding: Pipe Length (ft): 213.2 Owner: **City of Hobart** Pre Clean: **Heavy Cleaning** P.O.#: S. Bucklin PSR: P-504-039-038 YES502259 Surveyor:

Customer: **City of Hobart** Clean Date: 10/28/2021 Shape:

**North Colorado Street** Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed: Alley Tape/Media #: Location:

Purpose: **Routine Assessment** Dia/Height: 10" Use: **Sanitary Sewage Pipe** Material: **VCP** None

Drain Area: Lining:

Category: NA

Comment:


**Location Details:** Direction of Survey: **Downstream** 

US MH: M-504-038 DS MH: M-504-039 Total Length Surveyed (ft): 213.2

2.21 31.00 O&M Index: O&M Quick: O&M Rating: 2.20 44.00 Structural Rating: Structural Index: Structural Quick: 2.21 4432 75.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
M(504-)0	38				
	0. //	AMH	Manhole	1	NA
- 11	\.0	MWL	Miscellaneous Water Level	63	NA
	11.0	MWLS(S01)	Miscellaneous Water Level Sag	126	S 2
- 11	27.3	MWLS(F01)	Miscellaneous Water Level Sag	189	S 2
- 11	28.9	MMC	Miscellaneous Material Change	236	NA
- 11	//31.6	TF	Tap Factory	265	NA
	31.7	TF	Tap Factory	295	NA
	31.7	MMC	Miscellaneous Material Change	349	NA
	33.8	MWLS(S02)	Miscellaneous Water Level Sag	383	S 2
§	41.3	MWLS(F02)	Miscellaneous Water Level Sag	431	S 2
Camera Direction	42.2	DAE	Deposits Attached Encrustation	459	M 2
i Di	44.8	MWLS(S03)	Miscellaneous Water Level Sag	494	S 2
era	52.3	В	Broken	572	S 4
Can	59.3	MWLS(F03)	Miscellaneous Water Level Sag	665	S 2
	61.4	LD	Line Down	694	M 1
	61.5	JAM	Joint Angular Medium	710	S 3
<b>↓</b> <u></u>	62.9	MWLS(S04)	Miscellaneous Water Level Sag	743	S 2
	67.8	MMC	Miscellaneous Material Change	821	NA
	69.7	TF	Tap Factory	867	NA

71.7	TF	Tap Factory	899	NA
73.0	MMC	Miscellaneous Material Change	951	NA
73.4	MWLS(F04)	Miscellaneous Water Level Sag	973	S 2
75.6	IRJ	Infiltration Runner Joint	1000	М
75.6	DAE	Deposits Attached Encrustation	1013	М
77.5	MWLS(S05)	Miscellaneous Water Level Sag	1041	S 2
104.0	MWLS(F05)	Miscellaneous Water Level Sag	1175	S 2
106.4	MMC	Miscellaneous Material Change	1219	NA
109.6	TF	Tap Factory	1264	NA
112.8	TF	Tap Factory	1314	NA
114.0	MMC	Miscellaneous Material Change	1387	NA
140.3	MWLS(S06)	Miscellaneous Water Level Sag	1581	S 2
/147.5	MWLS(F06)	Miscellaneous Water Level Sag	1623	S 2
//148.0	SZ	Surface Damage Other	1641	NA
///150.4	JOM	Joint Offset Medium	1676	S 3
// 150.6	MMC	Miscellaneous Material Change	1710	NA
150.7	SZ	Surface Damage Other	1731	NA
152.8	TF	Tap Factory	1766	NA
155.1	TF	Tap Factory	1798	NA
156.0	MMC	Miscellaneous Material Change	1844	NA
√\158.6	DAE	Deposits Attached Encrustation	1888	М
163.9	DAE	Deposits Attached Encrustation	1948	М
174.1	DAE	Deposits Attached Encrustation	2023	М
174.1	IRJ	Infiltration Runner Joint	2038	М
176.7	IRJ	Infiltration Runner Joint	2082	М
176.7	DAE	Deposits Attached Encrustation	2101	М
181.7	CL	Crack Longitudinal	2150	S 2
$\sqrt{\frac{184.4}{}}$	DAE	Deposits Attached Encrustation	2201	М
191.9	DAE	Deposits Attached Encrustation	2286	М
202.2	RFJ	Roots Fine Joint	2370	М
205.0	RFJ	Roots Fine Joint	2418	М
213.2	AMH	Manhole	2591	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-038



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 

Distance (ft): 11.0 Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 **S01** Continuous Index: Within 8" of Joint: NO

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 27.3 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: F01 Within 8" of Joint: NO

Remarks:



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 28.9
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: VCP TO PVC



Code: **TF** 

Description: Tap Factory

Distance (ft): 31.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11


Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.



Code: **TF** 

Description: Tap Factory

Distance (ft): 31.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2


Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 31.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: PVC TO VCP



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 33.8 Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: **S02** Within 8" of Joint: NO

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 41.3 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: F02 Within 8" of Joint: NO

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation** 

42.2 Distance (ft): Structural Grade: 0 2 O&M Grade: Clock Start/From: 3 Clock To: 8

1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 

Distance (ft): 44.8 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000 Continuous Index: S03 Within 8" of Joint: NO

Remarks:



Code: B
Description: Broken

Distance (ft): 52.3
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 9

Clock To: 2

1st Value: 2


2nd Value:

Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 59.3
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks:



Code: LD

Description: Line Down

Distance (ft): 61.4
Structural Grade: 0

O&M Grade: 1

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: JAM

Description: Joint Angular Medium

Distance (ft): 61.5
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 62.9
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S04
Within 8" of Joint: NO

Remarks:



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 67.8
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: VCP TO PVC



Code: **TF** 

Description: Tap Factory

Distance (ft): 69.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 71.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.

0.00 ft/min



Code: MMC

Description: **Miscellaneous Material Change** 


Distance (ft): 73.0 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **PVC TO VCP** 



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 73.4 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: F04 Within 8" of Joint: NO

Remarks:



IRJ Code:

Description: **Infiltration Runner Joint** 


Distance (ft): 75.6 Structural Grade: 0 O&M Grade: 4 Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: **Deposits Attached Encrustation** 

Distance (ft): 75.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 3 5 Clock To: 1st Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint:

Remarks:

2nd Value:

YES



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 

77.5 Distance (ft): Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: **S05** Within 8" of Joint: NO

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 104.0 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: F05 Within 8" of Joint: NO

Remarks:



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 106.4
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: VCP TO PVC



Code: TF

Description: Tap Factory

Distance (ft): 109.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2


Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.



Code: **TF** 

Description: Tap Factory

Distance (ft): 112.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES

0.00 ft/min

11/2/21 114.02 ft

Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 114.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: PVC TO VCP



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 140.3 Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 **S06** Continuous Index: Within 8" of Joint: NO

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 


Distance (ft): 147.5 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: F06 Within 8" of Joint: NO

Remarks:



Code: SZ

Description: Surface Damage Other

Distance (ft): 148.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: A PIECE CHIPPED AWAY FROM THE

**JOINT** 



Code: **JOM** 

Description: Joint Offset Medium

Distance (ft): 150.4
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 150.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: VCP TO PVC



Code: SZ

Description: Surface Damage Other


Distance (ft): 150.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2
Clock To: 4
1st Value:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: A COUPLE PIECES CHIPPED AWAY

FROM THE JOINT



Code: **TF** 

Description: Tap Factory

Distance (ft): 152.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1


Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY DRIPPING WATER.



Code: TF

Description: Tap Factory

Distance (ft): 155.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.

0.79 ft/min



Code: MMC

Description: **Miscellaneous Material Change** 

Distance (ft): 156.0 Structural Grade: 0 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **PVC TO VCP** 



Code: DAE

Description: **Deposits Attached Encrustation** 

5.000

Distance (ft): 158.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 4 Clock To: 5 1st Value:

2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation** 

Distance (ft): 163.9 Structural Grade: 0 2 O&M Grade: Clock Start/From: 7 Clock To: 8


1st Value: 2nd Value:

5.000 Value Percent:

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation** 

Distance (ft): 174.1 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 8 1st Value:

2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: YES

Remarks:

5.000



Code: IRJ

Description: Infiltration Runner Joint


Distance (ft): 174.1
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 8

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IRJ


Description: Infiltration Runner Joint

Distance (ft): 176.7
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 9

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation** 

Distance (ft): 176.7 Structural Grade: 0 2 O&M Grade: Clock Start/From: 7 Clock To: 9

1st Value: 2nd Value:


5.000 Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: **Crack Longitudinal** 


Distance (ft): 181.7 Structural Grade: 2 O&M Grade: 0

Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 184.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 8


1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 191.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To: 9
1st Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: RFJ

Description: Roots Fine Joint


Distance (ft): 202.2
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 10
Clock To: 1

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RFJ


Description: Roots Fine Joint

Distance (ft): 205.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 10
Clock To: 12
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 213.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-039