## **Profile/Photo Observation Report**



Date: 04/18/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 206.0 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-504-048-046 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N COLORADO ST & N DELAWARE ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Upstream** 

US MH: M-504-046 DS MH: M-504-048 Total Length Surveyed (ft): 11.3

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
M(504-)04	48				
	.0	AMH	Manhole	10	NA
,	\ <u>.</u> 0	MWL	Water Level	21	NA
- 1	11.3	MSA	Abandoned Survey	55	NA
Camera Direction	46				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-046

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

Code: MSA

Description: **Abandoned Survey** 



Distance (ft): 11.3 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: camera flipped