

Profile/Photo Observation Report						
Date:	04/19/2018	Weather:		Coding:	PACP 6.0	
Pipe Length (f	t): 166.1	Owner:	NA	Pre Clean:	Not Known	
P.O.#:		Surveyor:	Jen Costello	PSR:	P-504-050-049	
Customer:		Clean Date:	01/01/1900	Shape:	с	
Street:	N COLORADO ST		Flow Control:			
City:	Hobart, IN		Year Renewed:			
Location:	Light Highway		Tape/Media #:			
Purpose:	Not Known		Dia/Height:	10"		
Use:	Sanitary		Material:	VCP		
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details:			Direction of Surv	vey: Downstream		
US MH:	M-504-049	DS MH:	M-504-050	Total Length Surveyed (ft)	: 5.0	
0&M Index:	4.00	O&M Quick:	410	0 O&M Rating:	4.00	
structural Index	. 0.00	Structural Qu	iick: 000		0.00	
Overall Index:	4.00	Overall Quick	. 410		4.00	





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-049



Code: Description:

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 100.000 Continuous Index: Within 8" of Joint: NO Remarks:

MWL

Water Level



Code:	MCU	
Description:	Camera Underwater	

Distance (ft):	5.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	MSA



Code: Description: MSA Abandoned Survey

Distance (ft):	5.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	MCU