## **Profile/Photo Observation Report**

**Light Highway** 



Date: 04/20/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 184.3 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Byrd Fitzgerald** PSR: **P-504-065-065.1** 

01/01/1900

Tape/Media #:

Shape:

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed:

Clean Date:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Customer:

Location:

Location Details: Direction of Survey: **Downstream** 

US MH: M-504-065.1 DS MH: M-504-065 Total Length Surveyed (ft): 179.4

3.67 11.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 3.25 13.00 Overall Quick: Overall Rating: Overall Index:

	osition	Code	Observation	Video (sec)	Grade
04-065.1	i				
0.		AMH	Manhole	10	NA
0. //	)	MWL	Water Level	21	NA
2.	.3	CL	Crack Longitudinal	38	S 2
13	37.8	DSZ	Deposits Settled Other	321	M 3
16	67.9	DAE	Deposits Attached Encrustation	392	M 4
16	67.9	IR	Infil Runner	403	M 4
17	79.4	MSA	Abandoned Survey	438	NA
Ш					

Code:

Description:



Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Continuous Index:

AMH

Manhole

Within 8" of Joint: NO
Remarks: M-504-065.1



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: CL

Description: **Crack Longitudinal** 



Distance (ft): 2.3 Structural Grade: 2

O&M Grade: 0 Clock Start/From: 9

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:



Code: DSZ

Description: Deposits Settled Other

Distance (ft): 137.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks: debris/sediments



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 167.9
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value: Value Percent:

alue Percent: 25.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: IR

Description: Infil Runner

Distance (ft): 167.9
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 179.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stuck/no blockage