Profile/Photo Observation Report



Date: **PACP 7.0** 09/13/2021 Weather: Coding: Pipe Length (ft): 124.0 Owner: **City of Hobart** Pre Clean: **Light Cleaning** P.O.#: S. Bucklin PSR: P-504-065.2-065.1 YES502259 Surveyor:

Customer: City of Hobart Clean Date: 09/09/2021 Shape: C

Street: North Guyer Street Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Local rural streets with light traffic, t Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"
Use: Sanitary Sewage Pipe Material: CP
Drain Area: Lining: None

Category: NA


Comment:

Location Details: Direction of Survey: Upstream

US MH: M-504-065.1 DS MH: M-504-065.2 Total Length Surveyed (ft): 124.0

2.00 2G00 82.00 O&M Index: O&M Quick: O&M Rating: 2.38 31.00 Structural Quick: Structural Rating: Structural Index: 2.09 113.00 Overall Quick: Overall Index: Overall Rating:

Position	Code	Observation	Video (sec)	Grade
4-065.2				
.0	AMH	Manhole	1	NA
0./\	MWL	Miscellaneous Water Level	63	NA
5.4	DAR	Deposits Attached Ragging	130	M 2
19.4	В	Broken	233	S 4
19.4	DAE	Deposits Attached Encrustation	300	M 2
19.6	TB	Tap Break-in/Hammer	320	NA
23.4	DAE(S01)	Deposits Attached Encrustation	381	M 2
30.7	FS	Fracture Spiral	481	S 3
30.7	DAE	Deposits Attached Encrustation	503	M 2
38.1	MWLS(S02)	Miscellaneous Water Level Sag	552	S 2
39.9	DSF(S03)	Deposits Settled Fine	576	M 2
52.3	MWLS(F02)	Miscellaneous Water Level Sag	641	S 2
59.5	MWLS(S04)	Miscellaneous Water Level Sag	680	S 2
64.7	TF	Tap Factory	747	NA
69.6	FS	Fracture Spiral	831	S 3
69.6	DAE	Deposits Attached Encrustation	844	M 2
70.5	MWLS(F04)	Miscellaneous Water Level Sag	866	S 2
79.1	MWLS(S05)	Miscellaneous Water Level Sag	909	S 2
99.0	MWLS(F05)	Miscellaneous Water Level Sag	1013	S 2
106.0	JSM	Joint Separated Medium	1086	S 3
/115.9	MWL	Miscellaneous Water Level	1173	NA
123.0	TF	Tap Factory	1301	NA
//123.9	DSF(F03)	Deposits Settled Fine	1333	M 2
///123.9	DAE(F01)	Deposits Attached Encrustation	1341	M 2
124.0	AEP	Access Point End of Pipe	1385	NA



Code: AMH
Description: Manhole


Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-065.2



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Code: DAR

Description: Deposits Attached Ragging

Distance (ft): 5.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 5

Clock To: 7


1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: B

Description: Broken

Distance (ft): 19.4
Structural Grade: 4

O&M Grade: 0


Clock Start/From: 10

Clock To: 12

1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 19.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TB

Description: Tap Break-in/Hammer

Distance (ft): 19.6
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 23.4
Structural Grade: 0

O&M Grade: 2


Clock Start/From: 3

Clock To: 9

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: FS

Description: Fracture Spiral

Distance (ft): 30.7
Structural Grade: 3

O&M Grade: 0


Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value:

Value Percent:
Continuous Index:

Within 8" of Joint: NO



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 30.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 5

1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 38.1
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S02
Within 8" of Joint: NO



Code: **DSF**


Description: Deposits Settled Fine

Distance (ft): 39.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S03
Within 8" of Joint: YES

Remarks:



Code: MWLS


Description: Miscellaneous Water Level Sag

Distance (ft): 52.3
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F02
Within 8" of Joint: NO



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 59.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S04
Within 8" of Joint: NO

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 64.7
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **FS**

Description: Fracture Spiral


Distance (ft): 69.6
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 69.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 5

1st Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**


Distance (ft): 70.5 Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: F04 Within 8" of Joint: NO

Remarks:



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 79.1 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: **S05** Within 8" of Joint: NO



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 99.0 Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F05
Within 8" of Joint: NO

Remarks:



Code: JSM

Description: Joint Separated Medium

Distance (ft): 106.0
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): 115.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory


Distance (ft): 123.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **DSF**


Description: Deposits Settled Fine

Distance (ft): 123.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F03
Within 8" of Joint: YES

Remarks:



Code: DAE


Description: Deposits Attached Encrustation

Distance (ft): 123.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To: 9
1st Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

2nd Value:



Code: AEP

Description: Access Point End of Pipe

Distance (ft): 124.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-065.1