
Profile/Photo Observation Report



Profile/Photo Observation Report								
Date: Pipe Length (ft P.O.#: Customer:	04/08/2018): 21-2 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of H M. Pielad		Pre Clean: PSR:	PACP 6.0 No Pre-Cleaning M-504-075-M-504-074 C		
Street: Off Colorado Street City: Hobart, IN Location: Light Highway Purpose: Routine Assessment		Flow Control: Year Renewed: Tape/Media #: Dia/Height:		Not Controlled DEP 21 18"	DEP 21			
Use: Drain Area: Category: Comment:	Sanitary NA		Material: Lining:		VCP			
Location Detail US MH:	ls: M-504-075	DS MH:	Direction 6 M-504-074	of Survey:	Downstream Total Length Surveyed (ft):	222.7		
O&M Index:	3.00	_O&M Quick:		3400	O&M Rating:	12.00		
Structural Index:		_Structural Qu	uick:	0000	Structural Rating:	0.00		
Overall Index:	3.00	Overall Quicl	k:	3400	Overall Rating:	12.00		

	Position	Code	Observation	Video (sec)	Grade
504-07	75				
	.0	AMH	Manhole	0	NA
	\ <u>.0</u>	MWL	Water Level	7	NA
ш	80.3	TBA	Tap Break-in Active	104	NA
ш	122.1	ТВ	Tap Break-in	177	NA
ш	134.3	TBA	Tap Break-in Active	204	NA
	166.1	TBD	Tap Break-in Defective	255	M 3
	166.1	RML	Roots Medium Lateral	260	M 3
	208.7	OBZ	Obstacle Other	350	M 3
	221.0	RMJ	Roots Medium Joint	400	M 3
	222.7	AMH	Manhole	415	NA
	11				



Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-504-075		



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TBA

Description: Tap Break-in Active

Distance (ft): 80.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TB

Description: Tap Break-in

Distance (ft): 122.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TBA

Description: Tap Break-in Active

Distance (ft): 134.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TBD

Description: **Tap Break-in Defective**

Distance (ft): 166.1 Structural Grade: 0 3 O&M Grade: Clock Start/From: 12

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **Defective**



Code: **RML**

Description: **Roots Medium Lateral**

Distance (ft): 166.1 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 12

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

5 Thursday, May 4, 2023



Code: OBZ

Description: Obstacle Other

Distance (ft): 208.7
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO
Remarks: Debris



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 221.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 6
Clock To: 12
1st Value:

2nd Value:

Value Percent: 25.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

arks:



Code: AMH
Description: Manhole

Distance (ft): 222.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-074