Profile/Photo Observation Report



Date: 04/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 314.5 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-504-083-082 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Category: NA

Category: NA
Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-504-082 DS MH: M-504-083 Total Length Surveyed (ft): 213.1

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

| Position | Code | Observation | Video (sec) | Grade |
|----------|------|-------------------------|-------------|-------|
| 504-082 | | | | |
| .0 | AMH | Manhole | 10 | NA |
| 0. | MWL | Water Level | 21 | NA |
| 40.5 | TF | Tap Factory | 114 | NA |
| 40.5 | DAZ | Deposits Attached Other | 126 | M 2 |
| 73.3 | TF | Tap Factory | 203 | NA |
| /111.8 | TF | Tap Factory | 292 | NA |
| /114.2 | TF | Tap Factory | 309 | NA |
| 149.6 | TF | Tap Factory | 393 | NA |
| 153.6 | TF | Tap Factory | 413 | NA |
| 186.2 | TF | Tap Factory | 491 | NA |
| 213.1 | MSA | Abandoned Survey | 558 | NA |
| | | | | |
| | | | | |

Code:



| Description: | Manhole | | |
|---------------------|-----------|--|--|
| Distance (ft). | 0 | | |
| Distance (ft): | .0 | | |
| Structural Grade: | 0 | | |
| O&M Grade: | 0 | | |
| Clock Start/From: | | | |
| Clock To: | | | |
| 1st Value: | | | |
| 2nd Value: | | | |
| Value Percent: | | | |
| Continuous Index: | | | |
| Within 8" of Joint: | NO | | |
| Remarks: | M-504-082 | | |
| | | | |

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

11

Code: TF

Description: Tap Factory



Distance (ft): 40.5
Structural Grade: 0


O&M Grade: 0

Clock Start/From: Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 40.5
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 10

1st Value:

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory


Distance (ft): 73.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TF

Description: **Tap Factory**

Distance (ft): 111.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:


1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

YES

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 114.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TF

Description: **Tap Factory**

Distance (ft): 149.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

Code: TF

Description: **Tap Factory**

YES

11



Distance (ft): 153.6 Structural Grade: 0 O&M Grade: 0

Clock Start/From: Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TF

Description: **Tap Factory**

Distance (ft): 186.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

YES



Code: MSA

Description: **Abandoned Survey**

Distance (ft): 213.1 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera flipped