Profile/Photo Observation Report



Date: 04/18/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 167.1 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-504-090-089 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN N VIRGINIA ST & N Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-504-089 DS MH: M-504-090 Total Length Surveyed (ft): 25.1

1.00 1100 1.00 O&M Index: O&M Quick: O&M Rating: 3.20 16.00 Structural Quick: Structural Rating: Structural Index: 2.83 17.00 Overall Index: Overall Quick: Overall Rating:

	Code	Observation	Video (sec)	Grade
504-089				
0.	RFJ	Roots Fine Joint	10	M 1
.0	AMH	Manhole	22	NA
\\.0	MWL	Water Level	33	NA
3.3	CM(S01)	Crack Multiple	51	S 3
18.6	FM	Fracture Multiple	93	S 4
18.8	TF	Tap Factory	105	NA
21.4	TF	Tap Factory	123	NA
24.8	ТВ	Tap Break-in	142	NA
25.1	MSA	Abandoned Survey	154	NA
25.1	CM(F01)	Crack Multiple	165	S 3

Code:



Description:	Roots Fine Joir
Distance (ft): Structural Grade:	.0 0
O&M Grade:	1
Clock Start/From: Clock To:	12 2
1st Value:	
2nd Value: Value Percent:	
Continuous Index: Within 8" of Joint:	YES
Remarks:	IES

RFJ

Roots Fine Joint



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-089



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 3.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 10
Clock To: 5
1st Value:
2nd Value:

Value Percent:
Continuous Index: **S01**

Within 8" of Joint:

Remarks: wandering



Code: FM

Description: Fracture Multiple

YES

Distance (ft): 18.6
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 8
Clock To: 12
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 18.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 11

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TF

Description: **Tap Factory**

Distance (ft): 21.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 1

Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: TB

Description: Tap Break-in

Distance (ft): 24.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 25.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: no blockage



Code: CM

Description: Crack Multiple

Distance (ft): 25.1
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 10
Clock To: 5
1st Value:

2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks: wandering