Profile/Photo Observation Report



Date: 04/18/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 129.7 Owner: NA Pre Clean: **Not Known** P.O.#: **Michael Carlino** PSR: P-504-106-105 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-504-105 DS MH: M-504-106 Total Length Surveyed (ft): 124.8

1.56 3123 14.00 O&M Index: O&M Quick: O&M Rating: 3.50 7.00 Structural Quick: Structural Rating: Structural Index: 1.91 21.00 Overall Quick: Overall Rating: Overall Index:



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-105



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO



Code: TBD

Description: **Tap Break-in Defective**

Distance (ft): 28.7 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 11

Clock To:

1st Value: 6.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: **RFC**



Code: RFC

Description: Roots Fine Connection

Distance (ft): 28.7
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 11

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: FM

Description: Fracture Multiple

Distance (ft): 52.2
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 10

Clock To: 12

1st Value:

2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 52.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 12

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: FM; RFL



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 60.4
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 84.3
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 10

Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FL

Description: Fracture Longitudinal

Distance (ft): 85.0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 2
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: RFB

Description: Roots Fine Barrel

Distance (ft): 85.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: RFL

Description: Roots Fine Lateral

Distance (ft): 86.4
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 2

Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

NO



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 86.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 2

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: RFL



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 123.7
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 9

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 124.8
Structural Grade: 0

O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: RFJ