

Profile/Photo Observation Report



Date:	09/06/2021	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	205.3	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-504-118-117
Customer:	City of Hobart	Clean Date:	09/03/2021	Shape:	C

Street:	42nd Avenue	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Alley	Tape/Media #:	
Purpose:	Routine Assessment	Dia/Height:	12"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Upstream
US MH:	M-504-117	DS MH:	M-504-118
		Total Length Surveyed (ft):	205.3

O&M Index:	2.15	O&M Quick:	3C2H	O&M Rating:	181.00
Structural Index:	3.20	Structural Quick:	4B3D	Structural Rating:	157.00
Overall Index:	2.54	Overall Quick:	4B3I	Overall Rating:	338.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	73	NA
	.0	MWL	Miscellaneous Water Level	86	NA
	2.2	JOM	Joint Offset Medium	127	S 3
	2.2	RFJ(S01)	Roots Fine Joint	156	M 1
	2.2	FM	Fracture Multiple	176	S 4
	8.2	CM	Crack Multiple	273	S 3
	9.6	OBN	Obstruction Construction Debris	312	M 2
	12.6	JOM	Joint Offset Medium	350	S 3
	12.6	FM	Fracture Multiple	383	S 4
	16.9	DSF(S02)	Deposits Settled Fine	427	M 2
	19.1	FM	Fracture Multiple	478	S 4
	21.1	JOM	Joint Offset Medium	512	S 3
	21.1	FM	Fracture Multiple	542	S 4
	27.5	JOM	Joint Offset Medium	590	S 3
	27.5	CM	Crack Multiple	621	S 3
	33.5	CM	Crack Multiple	692	S 3
	44.0	FL	Fracture Longitudinal	759	S 3
	48.4	FM(S03)	Fracture Multiple	824	S 4
	51.4	DAE	Deposits Attached Encrustation	882	M 2

53.6	DAE	Deposits Attached Encrustation	934	M 2
53.7	RFJ(F01)	Roots Fine Joint	952	M 1
58.8	SSS	Surface Damage Surface Spalling	997	S 2
59.5	TBI	Tap Break-in Intruding	1016	M 2
61.0	TFD	Tap Factory Defective	1046	M 3
63.4	TFD	Tap Factory Defective	1077	M 3
64.5	FM(F03)	Fracture Multiple	1099	S 4
70.6	CS	Crack Spiral	1134	S 2
72.9	DAE	Deposits Attached Encrustation	1186	M 2
74.4	JOM	Joint Offset Medium	1211	S 3
78.8	JOM	Joint Offset Medium	1243	S 3
78.8	MWLS	Miscellaneous Water Level Sag	1257	S 2
83.2	DAE	Deposits Attached Encrustation	1302	M 2
85.2	JOM	Joint Offset Medium	1328	S 3
88.8	SSS	Surface Damage Surface Spalling	1370	S 2
89.4	TBI	Tap Break-in Intruding	1391	M 2
91.7	DAE	Deposits Attached Encrustation	1431	M 2
95.9	JOM	Joint Offset Medium	1464	S 3
99.8	OBN	Obstruction Construction Debris	1506	M 2
100.9	CM	Crack Multiple	1573	S 3
101.3	TBD	Tap Break-in/Hammer Defective	1594	M 3
108.7	JOM	Joint Offset Medium	1650	S 3
111.1	DAE	Deposits Attached Encrustation	1696	M 2
112.3	TFD	Tap Factory Defective	1728	M 3
112.3	CM	Crack Multiple	1759	S 3
112.7	JOM	Joint Offset Medium	1773	S 3
114.6	TFD	Tap Factory Defective	1800	M 3
114.6	CM	Crack Multiple	1838	S 3
121.3	JOM	Joint Offset Medium	1881	S 3
123.8	DAE	Deposits Attached Encrustation	1935	M 2
127.7	JOM	Joint Offset Medium	1970	S 3
127.7	RFJ	Roots Fine Joint	1991	M 1
127.7	FS	Fracture Spiral	2017	S 3
130.1	RMJ(S04)	Roots Medium Joint	2080	M 3
130.1	FM(S05)	Fracture Multiple	2118	S 4
138.4	JOM	Joint Offset Medium	2163	S 3
146.9	JOM	Joint Offset Medium	2224	S 3
151.4	JOM	Joint Offset Medium	2270	S 3
157.1	SSS	Surface Damage Surface Spalling	2370	S 2
157.1	RML	Roots Medium Lateral	2383	M 3
157.5	TBI	Tap Break-in Intruding	2409	M 2
160.4	RML	Roots Medium Lateral	2462	M 3


160.5	SSS	Surface Damage Surface Spalling	2485	S 2
163.7	TFD	Tap Factory Defective	2573	M 3
164.1	FM(F05)	Fracture Multiple	2600	S 4
165.7	TFD	Tap Factory Defective	2624	M 3
176.6	JOM	Joint Offset Medium	2683	S 3
183.1	JOM	Joint Offset Medium	2723	S 3
189.6	JOM	Joint Offset Medium	2760	S 3
193.9	JOM	Joint Offset Medium	2792	S 3
193.9	FM(S06)	Fracture Multiple	2815	S 4
203.2	FM(F06)	Fracture Multiple	2918	S 4
203.2	RMJ(F04)	Roots Medium Joint	2926	M 3
203.2	DSF(F02)	Deposits Settled Fine	2934	M 2
205.3	AMH	Manhole	3002	NA

M-504-117




Code: **AMH**
Description: **Manhole**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-504-118**




Code: **MWL**
 Description: **Miscellaneous Water Level**

Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **10.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **2.2**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **RFJ**
Description: **Roots Fine Joint**

Distance (ft): **2.2**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From: **10**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S01**
Within 8" of Joint: **YES**
Remarks:




Code: **FM**
Description: **Fracture Multiple**

Distance (ft): **2.2**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **9**
Clock To: **10**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **CM**
 Description: **Crack Multiple**

Distance (ft): **8.2**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From: **12**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **OBN**
 Description: **Obstruction Construction Debris**

Distance (ft): **9.6**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **7**
 Clock To: **8**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **12.6**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **FM**
 Description: **Fracture Multiple**

Distance (ft): **12.6**
 Structural Grade: **4**
 O&M Grade: **0**
 Clock Start/From: **9**
 Clock To: **1**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **DSF**
 Description: **Deposits Settled Fine**

Distance (ft): **16.9**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **5**
 Clock To: **7**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index: **S02**
 Within 8" of Joint: **YES**
 Remarks:




Code: **FM**
 Description: **Fracture Multiple**

Distance (ft): **19.1**
 Structural Grade: **4**
 O&M Grade: **0**
 Clock Start/From: **10**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:



Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **21.1**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **FM**
 Description: **Fracture Multiple**

Distance (ft): **21.1**
 Structural Grade: **4**
 O&M Grade: **0**
 Clock Start/From: **10**
 Clock To: **2**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **27.5**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **CM**
 Description: **Crack Multiple**

Distance (ft): **27.5**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From: **12**
 Clock To: **4**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **CM**
Description: **Crack Multiple**

Distance (ft): **33.5**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **8**
Clock To: **1**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **FL**
Description: **Fracture Longitudinal**

Distance (ft): **44.0**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **12**
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **FM**
 Description: **Fracture Multiple**

Distance (ft): **48.4**
 Structural Grade: **4**
 O&M Grade: **0**
 Clock Start/From: **10**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index: **S03**
 Within 8" of Joint: **YES**
 Remarks:




Code: **DAE**
 Description: **Deposits Attached Encrustation**

Distance (ft): **51.4**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **4**
 Clock To: **8**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **DAE**
 Description: **Deposits Attached Encrustation**

Distance (ft): **53.6**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **4**
 Clock To: **9**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **RFJ**
 Description: **Roots Fine Joint**

Distance (ft): **53.7**
 Structural Grade: **0**
 O&M Grade: **1**
 Clock Start/From: **10**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index: **F01**
 Within 8" of Joint: **YES**
 Remarks:



Code: **SSS**
Description: **Surface Damage Surface Spalling**

Distance (ft): **58.8**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **TBI**
Description: **Tap Break-in Intruding**

Distance (ft): **59.5**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **11**
Clock To:
1st Value: **6.000**
2nd Value: **1.000**
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **CONSTANTLY RUNNING WATER**




Code: **TFD**
Description: **Tap Factory Defective**

Distance (ft): **61.0**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **11**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **CAPPED**




Code: **TFD**
Description: **Tap Factory Defective**

Distance (ft): **63.4**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **1**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **CONSTANTLY RUNNING WATER**




Code: **FM**
Description: **Fracture Multiple**

Distance (ft): **64.5**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F03**
Within 8" of Joint: **YES**
Remarks:




Code: **CS**
Description: **Crack Spiral**


Distance (ft): **70.6**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **2**
Clock To: **4**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code:	DAE
Description:	Deposits Attached Encrustation
Distance (ft):	72.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	3
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	JOM
Description:	Joint Offset Medium
Distance (ft):	74.4
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **78.8**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**


Distance (ft): **78.8**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code:	DAE
Description:	Deposits Attached Encrustation
Distance (ft):	83.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	4
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	JOM
Description:	Joint Offset Medium
Distance (ft):	85.2
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	SSS
Description:	Surface Damage Surface Spalling
Distance (ft):	88.8
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	12
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	TBI
Description:	Tap Break-in Intruding
Distance (ft):	89.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	
1st Value:	6.000
2nd Value:	2.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: **DAE**
 Description: **Deposits Attached Encrustation**

Distance (ft): **91.7**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **4**
 Clock To: **7**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**


Distance (ft): **95.9**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code:	OBN
Description:	Obstruction Construction Debris
Distance (ft):	99.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	5
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	CM
Description:	Crack Multiple
Distance (ft):	100.9
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	11
Clock To:	1
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: **TBD**
 Description: **Tap Break-in/Hammer Defective**

Distance (ft): **101.3**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **11**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks: **Defective**




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **108.7**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **DAE**
Description: **Deposits Attached Encrustation**

Distance (ft): **111.1**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **3**
Clock To: **9**
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **TFD**
Description: **Tap Factory Defective**

Distance (ft): **112.3**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **11**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **CAPPED**




Code: **CM**
Description: **Crack Multiple**

Distance (ft): **112.3**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **11**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **112.7**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **TFD**
 Description: **Tap Factory Defective**

Distance (ft): **114.6**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **1**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks: **CAPPED**




Code: **CM**
 Description: **Crack Multiple**

Distance (ft): **114.6**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From: **1**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **121.3**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **DAE**
 Description: **Deposits Attached Encrustation**

Distance (ft): **123.8**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **4**
 Clock To: **8**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **127.7**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **RFJ**
 Description: **Roots Fine Joint**

Distance (ft): **127.7**
 Structural Grade: **0**
 O&M Grade: **1**
 Clock Start/From: **12**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **FS**
 Description: **Fracture Spiral**

Distance (ft): **127.7**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From: **1**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:



Code: **RMJ**
 Description: **Roots Medium Joint**

Distance (ft): **130.1**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **8**
 Clock To: **4**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index: **S04**
 Within 8" of Joint: **YES**
 Remarks:




Code: **FM**
Description: **Fracture Multiple**

Distance (ft): **130.1**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S05**
Within 8" of Joint: **YES**
Remarks:




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **138.4**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **146.9**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **JOM**
 Description: **Joint Offset Medium**

Distance (ft): **151.4**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **SSS**
 Description: **Surface Damage Surface Spalling**

Distance (ft): **157.1**
 Structural Grade: **2**
 O&M Grade: **0**
 Clock Start/From: **1**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **RML**
 Description: **Roots Medium Lateral**

Distance (ft): **157.1**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **1**
 Clock To: **2**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code:	TBI
Description:	Tap Break-in Intruding
Distance (ft):	157.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	2
Clock To:	
1st Value:	6.000
2nd Value:	1.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	CONSTANTLY RUNNING WATER. TAP LOOKS TO BE 90%+ PLUGGED WITH




Code:	RML
Description:	Roots Medium Lateral
Distance (ft):	160.4
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	9
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	40.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	SSS
Description:	Surface Damage Surface Spalling
Distance (ft):	160.5
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	10
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	TFD
Description:	Tap Factory Defective
Distance (ft):	163.7
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	11
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	ROOTS GROWING IN THE JOINT




Code: **FM**
Description: **Fracture Multiple**

Distance (ft): **164.1**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F05**
Within 8" of Joint: **YES**
Remarks:




Code: **TFD**
Description: **Tap Factory Defective**

Distance (ft): **165.7**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **1**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **CAPPED. ROOTS GROWING IN THE JOINT**




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **176.6**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **183.1**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **189.6**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **JOM**
Description: **Joint Offset Medium**

Distance (ft): **193.9**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **FM**
Description: **Fracture Multiple**

Distance (ft): **193.9**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S06**
Within 8" of Joint: **YES**
Remarks:



Code: **FM**
Description: **Fracture Multiple**

Distance (ft): **203.2**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **10**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F06**
Within 8" of Joint: **YES**
Remarks:



Code: **RMJ**
 Description: **Roots Medium Joint**

Distance (ft): **203.2**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **8**
 Clock To: **4**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index: **F04**
 Within 8" of Joint: **YES**
 Remarks:



Code: **DSF**
 Description: **Deposits Settled Fine**

Distance (ft): **203.2**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **5**
 Clock To: **7**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index: **F02**
 Within 8" of Joint: **YES**
 Remarks:



Code:	AMH
Description:	Manhole
Distance (ft):	205.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-117