Profile/Photo Observation Report



Date: 04/17/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 211.6 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-504-120-119 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Location Details: Direction of Survey: Upstream

US MH: M-504-119 DS MH: M-504-120 Total Length Surveyed (ft): 56.1

2.00 2A00 24.00 O&M Index: O&M Quick: O&M Rating: 3.00 3A00 33.00 Structural Quick: Structural Rating: Structural Index: 3A2A 2.48 57.00 Overall Quick: Overall Rating: Overall Index:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-119

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: DSZ

Description: **Deposits Settled Other**



Distance (ft): .0

Structural Grade: 0 O&M Grade: 2 Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks: debris/sediments



Code: CM

Description: Crack Multiple

Distance (ft): 2.5
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value: Value Percent:

Continuous Index: S02
Within 8" of Joint: YES

Remarks: wandering



Code: TB

Description: Tap Break-in

Distance (ft): 19.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 48.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

.....

YES

Remarks:



Code: **TFC**

Description: Tap Factory Capped

Distance (ft): 51.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: TBI

Description: Tap Break-in Intruding

Distance (ft): 54.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3

Clock To:

 1st Value:
 4.000

 2nd Value:
 3.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Abandoned Survey



Distance (ft): 56.1
Structural Grade: 0

O&M Grade: **0** Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: tbi



Code: CM

Description: Crack Multiple

Distance (ft): 56.1
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value: Value Percent:

Continuous Index: F02
Within 8" of Joint: YES

Remarks: wandering



Code: **DSZ**

Description: Deposits Settled Other

Distance (ft): 56.1
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 6

Clock To:
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks: debris/sediments