## **Profile/Photo Observation Report**



P-504-126.1-126

PSR:

Date: 04/16/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 320.0 Owner: NA Pre Clean: Not Known

Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

Surveyor:

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: CP

Drain Area: NA Lining:

Category: NA

Comment:

P.O.#:

Location Details: Direction of Survey: **Downstream** 

US MH: M-504-126 DS MH: M-504-126.1 Total Length Surveyed (ft): 4.8

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 3.00 3100 3.00 Structural Quick: Structural Rating: Structural Index: 3100 3.00 3.00 Overall Quick: Overall Rating: Overall Index:


	Position	Code	Observation	Video (sec)	Grade
M(504-)1	26				
	.0	SAP	Surface Aggregate Projecting	10	S 3
	.0	MMC	Material Change	22	NA
- 11	<u>√</u> .0	AMH	Manhole	33	NA
- 11	\.0	MWL	Water Level	44	NA
- 11	4.8	MSA	Abandoned Survey	65	NA
Camera Direction					
M-\$04- <b>)</b> 2	26.1				

Code:



Description: **Surface Aggregate Projecting** Distance (ft): .0 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-504-126.1

SAP



Code: MMC

Description: **Material Change** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO **VCP** Remarks:



Code: AMH Description: Manhole

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-504-126



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 4.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped