


# Profile/Photo Observation Report



Date:	09/03/2021	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	277.0	Owner:	City of Hobart	Pre Clean:	Light Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-504-126.1-126
Customer:	City of Hobart	Clean Date:	08/30/2021	Shape:	C

Street:	Old Ridge Road	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Alley	Tape/Media #:	
Purpose:	Routine Assessment	Dia/Height:	10"
Use:	Sanitary Sewage Pipe	Material:	CP
Drain Area:		Lining:	
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Downstream
US MH:	M-504-126	DS MH:	M-504-126.1
		Total Length Surveyed (ft):	277.0

O&M Index:	1.79	O&M Quick:	312N	O&M Rating:	184.00
Structural Index:	2.85	Structural Quick:	5243	Structural Rating:	94.00
Overall Index:	2.04	Overall Quick:	5243	Overall Rating:	278.00

Position	Code	Observation	Video (sec)	Grade
				
.0	AMH	Manhole	1	NA
.0	MWL	Miscellaneous Water Level	69	NA
.0	DSF(S01)	Deposits Settled Fine	83	M 2
2.7	RFJ	Roots Fine Joint	142	M 1
2.7	SMW	Surface Damage Missing Wall	178	S 5
2.7	B	Broken	208	S 4
2.7	MMC	Miscellaneous Material Change	225	NA
5.4	MMC	Miscellaneous Material Change	295	NA
5.4	FM	Fracture Multiple	338	S 4
7.5	MWLS(S02)	Miscellaneous Water Level Sag	383	S 2
8.6	MMC	Miscellaneous Material Change	429	NA
11.4	RFJ	Roots Fine Joint	517	M 1
11.4	RFJ	Roots Fine Joint	535	M 1
11.4	CL	Crack Longitudinal	578	S 2
11.4	CL	Crack Longitudinal	592	S 2
17.4	DAE	Deposits Attached Encrustation	653	M 2
20.6	RFJ	Roots Fine Joint	694	M 1
20.6	CM	Crack Multiple	772	S 3
23.5	CM(S03)	Crack Multiple	839	S 3


29.6	MWLS(F02)	Miscellaneous Water Level Sag	953	S 2
32.3	MWLS	Miscellaneous Water Level Sag	981	S 2
35.7	MMC	Miscellaneous Material Change	1037	NA
37.2	TBI	Tap Break-in Intruding	1087	M 2
40.2	TBI	Tap Break-in Intruding	1141	M 2
41.8	MMC	Miscellaneous Material Change	1195	NA
41.8	CM(F03)	Crack Multiple	1207	S 3
47.7	RFJ	Roots Fine Joint	1256	M 1
53.6	RFJ	Roots Fine Joint	1321	M 1
53.6	CM	Crack Multiple	1374	S 3
59.8	RMJ	Roots Medium Joint	1469	M 3
62.8	RFJ	Roots Fine Joint	1532	M 1
65.6	RFJ	Roots Fine Joint	1582	M 1
65.6	DAE	Deposits Attached Encrustation	1596	M 2
65.6	CL	Crack Longitudinal	1616	S 2
68.6	CM	Crack Multiple	1690	S 3
71.8	RFJ	Roots Fine Joint	1734	M 1
71.8	MMC	Miscellaneous Material Change	1754	NA
94.1	TBI	Tap Break-in Intruding	1921	M 2
97.1	TBI	Tap Break-in Intruding	2004	M 2
97.1	FC	Fracture Circumferential	2072	S 2
102.1	CM	Crack Multiple	2134	S 3
102.1	MMC	Miscellaneous Material Change	2157	NA
102.9	TFC	Tap Factory Capped	2186	NA
105.2	MMC	Miscellaneous Material Change	2240	NA
108.1	RFJ	Roots Fine Joint	2321	M 1
114.1	MWLS(S04)	Miscellaneous Water Level Sag	2376	S 2
119.4	TBI	Tap Break-in Intruding	2438	M 2
125.6	MWLS(F04)	Miscellaneous Water Level Sag	2481	S 2
129.7	CM	Crack Multiple	2536	S 3
138.4	MMC	Miscellaneous Material Change	2640	NA
138.4	CM	Crack Multiple	2676	S 3
139.3	TF	Tap Factory	2702	NA
141.5	MMC	Miscellaneous Material Change	2752	NA
147.4	MMC	Miscellaneous Material Change	2839	NA
148.3	TFC	Tap Factory Capped	2866	NA
150.4	MMC	Miscellaneous Material Change	2929	NA
150.4	FM	Fracture Multiple	2970	S 4
155.0	TBI	Tap Break-in Intruding	3029	M 2
159.4	DAE	Deposits Attached Encrustation	3118	M 2
165.5	DAE	Deposits Attached Encrustation	3179	M 2
165.5	DAE	Deposits Attached Encrustation	3195	M 2

168.5	DAE	Deposits Attached Encrustation	3231	M 2
171.8	JAM	Joint Angular Medium	3321	S 3
171.8	DAE	Deposits Attached Encrustation	3360	M 2
171.8	LL	Line Left	3383	M 1
171.9	DAE	Deposits Attached Encrustation	3459	M 2
171.9	CM	Crack Multiple	3479	S 3
177.6	DAE	Deposits Attached Encrustation	3536	M 2
177.6	DAE	Deposits Attached Encrustation	3553	M 2
180.7	DAE	Deposits Attached Encrustation	3588	M 2
190.1	CM	Crack Multiple	3672	S 3
195.9	DAE	Deposits Attached Encrustation	3736	M 2
198.8	DAE	Deposits Attached Encrustation	3789	M 2
198.8	LR	Line Right	3815	M 1
204.8	RFJ	Roots Fine Joint	3880	M 1
204.8	LL	Line Left	3907	M 1
208.0	RFJ	Roots Fine Joint	3948	M 1
214.3	CS	Crack Spiral	4032	S 2
217.1	RFJ	Roots Fine Joint	4077	M 1
223.1	MMC	Miscellaneous Material Change	4144	NA
224.1	TFC	Tap Factory Capped	4174	NA
226.1	MMC	Miscellaneous Material Change	4227	NA
228.6	TB	Tap Break-in/Hammer	4286	NA
229.1	RFJ	Roots Fine Joint	4338	M 1
229.1	DAE	Deposits Attached Encrustation	4369	M 2
232.2	RFJ	Roots Fine Joint	4415	M 1
238.3	RFJ	Roots Fine Joint	4461	M 1
241.3	MMC	Miscellaneous Material Change	4519	NA
242.2	TFC	Tap Factory Capped	4550	NA
244.3	RFJ	Roots Fine Joint	4608	M 1
244.3	CM	Crack Multiple	4645	S 3
245.3	TF	Tap Factory	4672	NA
247.4	MMC	Miscellaneous Material Change	4724	NA
250.3	DAE	Deposits Attached Encrustation	4771	M 2
253.5	RFJ	Roots Fine Joint	4825	M 1
253.5	RFJ	Roots Fine Joint	4844	M 1
256.5	RFJ	Roots Fine Joint	4889	M 1
259.3	DAE	Deposits Attached Encrustation	4944	M 2
265.5	DAE	Deposits Attached Encrustation	4999	M 2
267.2	CM	Crack Multiple	5061	S 3
268.3	DAE	Deposits Attached Encrustation	5093	M 2
271.4	BSV	Broken Soil Visible	5183	S 5
271.4	JOMD	Joint Offset Medium Defective	5205	S 3



277.0	DSF(F01)	Deposits Settled Fine	5315	M 2
277.0	AMH	Manhole	5323	NA

**M-504-126.1**



Code: **AMH**  
Description: **Manhole**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-504-126**



Code: **MWL**  
Description: **Miscellaneous Water Level**


Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:






Code: **DSF**  
 Description: **Deposits Settled Fine**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **S01**  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **2.7**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **3**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **SMW**  
 Description: **Surface Damage Missing Wall**

Distance (ft): **2.7**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **INSIDE OF THE JOINT**




Code: **B**  
 Description: **Broken**

Distance (ft): **2.7**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **OUTSIDE OF THE JOINT**



Code: **MMC**  
 Description: **Miscellaneous Material Change**


Distance (ft): **2.7**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**



Code: **MMC**  
 Description: **Miscellaneous Material Change**


Distance (ft): **5.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**






Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **5.4**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**


Distance (ft): **7.5**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **15.000**  
 Continuous Index: **S02**  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **8.6**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**


---



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **11.4**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **2**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **11.4**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **CL**  
 Description: **Crack Longitudinal**


Distance (ft): **11.4**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **CL**  
 Description: **Crack Longitudinal**

Distance (ft): **11.4**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **17.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **20.6**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **20.6**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **23.5**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **S03**  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **29.6**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **15.000**  
 Continuous Index: **F02**  
 Within 8" of Joint: **NO**  
 Remarks:






Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **32.3**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MMC**  
Description: **Miscellaneous Material Change**


Distance (ft): **35.7**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **VCP TO CONCRETE**

---




Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **37.2**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **40.2**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **LOOKS TO BE PLUGGED OFF**



Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **41.8**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**



Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **41.8**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **F03**  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **47.7**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To: **9**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **53.6**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **1**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **53.6**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RMJ**  
 Description: **Roots Medium Joint**

Distance (ft): **59.8**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **9**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **62.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **65.6**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **65.6**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **9**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **CL**  
 Description: **Crack Longitudinal**

Distance (ft): **65.6**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **68.6**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **71.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MMC**  
 Description: **Miscellaneous Material Change**


Distance (ft): **71.8**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**



Code: **TBI**  
 Description: **Tap Break-in Intruding**


Distance (ft): **94.1**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **ROCK BLOCKING THE TAP**






Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **97.1**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **FC**  
 Description: **Fracture Circumferential**

Distance (ft): **97.1**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **102.1**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MMC**  
 Description: **Miscellaneous Material Change**


Distance (ft): **102.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**






Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **102.9**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **105.2**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **108.1**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **114.1**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index: **S04**  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **TBI**  
 Description: **Tap Break-in Intruding**


Distance (ft): **119.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **12**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **3.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**


Distance (ft): **125.6**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index: **F04**  
 Within 8" of Joint: **NO**  
 Remarks:





Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **129.7**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **138.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**






Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **138.4**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---



Code: **TF**  
 Description: **Tap Factory**


Distance (ft): **139.3**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---




Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **141.5**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**




Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **147.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**



Code: **TFC**  
 Description: **Tap Factory Capped**


Distance (ft): **148.3**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **150.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**






Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **150.4**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **OUTSIDE OF THE BELL**




Code: **TBI**  
 Description: **Tap Break-in Intruding**

Distance (ft): **155.0**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **12**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value: **1.000**  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONSTANTLY RUNNING WATER**



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **159.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **165.5**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **165.5**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **7**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **168.5**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **JAM**  
 Description: **Joint Angular Medium**

Distance (ft): **171.8**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **171.8**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **LL**  
 Description: **Line Left**


Distance (ft): **171.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **171.9**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **171.9**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **177.6**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **177.6**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **180.7**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **3**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **CM**  
 Description: **Crack Multiple**


Distance (ft): **190.1**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **195.9**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **198.8**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **LR**  
 Description: **Line Right**

Distance (ft): **198.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:






Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **204.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **3**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **LL**  
 Description: **Line Left**

Distance (ft): **204.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **208.0**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **CS**  
 Description: **Crack Spiral**


Distance (ft): **214.3**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:





Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **217.1**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To: **9**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MMC**  
 Description: **Miscellaneous Material Change**


Distance (ft): **223.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **CONCRETE TO VCP**






Code: **TFC**  
 Description: **Tap Factory Capped**

Distance (ft): **224.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **226.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**



Code: **TB**  
 Description: **Tap Break-in/Hammer**


Distance (ft): **228.6**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **229.1**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **229.1**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **232.2**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **3**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **RFJ**  
Description: **Roots Fine Joint**

Distance (ft): **238.3**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **4**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:



Code: **MMC**  
Description: **Miscellaneous Material Change**


Distance (ft): **241.3**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **CONCRETE TO VCP**



Code:	<b>TFC</b>
Description:	<b>Tap Factory Capped</b>
Distance (ft):	<b>242.2</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>6.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>ROOTS GROWING AROUND THE CAP</b>




Code:	<b>RFJ</b>
Description:	<b>Roots Fine Joint</b>
Distance (ft):	<b>244.3</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>1</b>
Clock Start/From:	<b>8</b>
Clock To:	<b>4</b>
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	



Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **244.3**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---




Code: **TF**  
 Description: **Tap Factory**

Distance (ft): **245.3**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **6.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:


---






Code: **MMC**  
 Description: **Miscellaneous Material Change**

Distance (ft): **247.4**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **VCP TO CONCRETE**



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **250.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
Description: **Roots Fine Joint**

Distance (ft): **253.5**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **8**  
Clock To: **9**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **RFJ**  
Description: **Roots Fine Joint**

Distance (ft): **253.5**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **4**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---





Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **256.5**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **8**  
 Clock To: **9**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **259.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **265.5**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **267.2**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **268.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **BSV**  
 Description: **Broken Soil Visible**

Distance (ft): **271.4**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **JOMD**  
Description: **Joint Offset Medium Defective**

Distance (ft): **271.4**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **SOIL VISIBLE**

---




Code: **DSF**  
Description: **Deposits Settled Fine**

Distance (ft): **277.0**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **5**  
Clock To: **7**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index: **F01**  
Within 8" of Joint: **YES**  
Remarks:

---





Code:	AMH
Description:	Manhole
Distance (ft):	277.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-126.1