
Date:	04/16/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft):	315.0	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honu		PSR:	P-504-126-127
Customer:		Clean Date:	01/01/1900		Shape:	С
Street:	Summerlin		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed	1		
Location:	Light Highway		Tape/Media #:			
Purpose:	Not Known		Dia/Height:		10"	
Use:	Sanitary		Material:		СР	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details:			Direction of Su	rvey:	Upstream	
US MH:	M-504-127	DS MH:	M-504-126	Total	Length Surveyed (ft)	6.7
D&M Index:	0.00	O&M Quick:	00	000	O&M Rating:	0.00
Structural Index:	3.00	Structural Qu	uick: 31	100	Structural Rating:	3.00
Overall Index:	3.00	Overall Quick	2	00	Overall Rating:	3.00





Code: Description:	SAP Surface Aggregate Projecting
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	.0 3 0 8 4
Within 8" of Joint: Remarks:	



Code: Description:

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-504-127

AMH

Manhole



Code:	MWL
Description:	Water Level
Distance (ft):	.0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MMC Material Change
Distance (ft):	6.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO

VCP



Code:	MSA
Description:	Abandoned Survey

Remarks:

Distance (ft):	6.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped