Profile/Photo Observation Report

2.00

2.00

Structural Quick:

Overall Quick:

Structural Index:

Overall Index:



14.00

72.00

Date: 08/09/2022 Weather: **PACP 7.0** Coding: Pipe Length (ft): 169.0 Owner: **City of Hobart** Pre Clean: **Heavy Cleaning** P.O.#: YES502259 S. Bucklin PSR: P-505-010-008 Surveyor: Customer: **City of Hobart** Clean Date: 07/20/2022 Shape: **Lake George Drive** Flow Control: **Not Controlled** Street: City: Hobart, IN Year Renewed: Local rural streets with light traffic, t Tape/Media #: Location: Purpose: **Routine Assessment** Dia/Height: 15" Use: **Sanitary Sewage Pipe** Material: **VCP** Drain Area: Lining: None Category: NA Comment: **Location Details:** Direction of Survey: **Downstream** US MH: M-505-008 DS MH: M-505-010 Total Length Surveyed (ft): 167.8 2.00 2D00 58.00 O&M Index: O&M Quick: **O&M** Rating:

2700

2F00

Structural Rating:

Overall Rating:



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-505-008



Code: MWL

Description: **Miscellaneous Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 22.2 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks:

3 Tuesday, April 25, 2023



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 22.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: YES

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 46.6
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: SSS

Description: Surface Damage Surface Spalling


Distance (ft): 67.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 1

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TS

Description: Tap Saddle

Distance (ft): 67.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 12

Clock To:

2nd Value:

1st Value: **4.000**

Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 74.8
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF

Description: Tap Factory

Distance (ft): 122.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CONSTANTLY RUNNING WATER.



Code: **DSF**


Description: Deposits Settled Fine

Distance (ft): 165.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F02
Within 8" of Joint: YES

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 167.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-505-010