
Profile/Photo Observation Report



Profile/Photo Observation Report									
Date: Pipe Length (ft P.O.#: Customer:	04/27/2018 :): 124 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hoba M. Pielacha	rt	Coding: Pre Clean: PSR: Shape:	PACP 6.0 Not Known P-505-043-040 C			
Street: 2nd Street + Virginia		nia Street	Flow Control:		Not Controlled				
City:	Hobart, IN		Year Renewed	:					
Location:	Light Highway		Tape/Media#	:	124				
Purpose:	Routine Assessme	nt	Dia/Height:		18"				
Use:	Sanitary		Material:		VCP				
Drain Area:			Lining:						
Category:	NA								
Comment:	YES501824 Submi	tal 2							
Location Detai	ls:		Direction of Su	ırvey:	Downstream				
US MH:	M-505-040	DS MH:	M-505-043	Tota	al Length Surveyed (ft)	: 162.4			
D&M Index:	2.75	O&M Quick:	4	132	O&M Rating:	11.00			
structural Index:	0.00	Structural Qu	ick: 0	000	Structural Rating:	0.00			
Overall Index:	2.75	Overall Quick	. 4	132	Overall Rating:	11.00			

Thursday, May 4, 2023

Position	Code	Observation	Video (sec)	Grade
505-040				
.0 AMH		Manhole	0	NA
0.	MWL	Water Level	20	NA
5.7	OBZ	Obstacle Other	88	M 4
59.2	RMJ(S01)	Roots Medium Joint	541	M 3
69.6	RMJ(F01)	Roots Medium Joint	683	M 3
81.8	RFJ	Roots Fine Joint	746	M 1
91.7	TF	Tap Factory	866	NA
94.3	TF	Tap Factory	926	NA
106.7	MWL	Water Level	975	NA
162.4	AMH	Manhole	1165	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: NO

Remarks: **M-505-040**



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: OBZ

Description: Obstacle Other

Distance (ft): 5.7
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 3
Clock To: 8
1st Value:
2nd Value:

Value Percent: 25.000

Continuous Index:

Within 8" of Joint: NO
Remarks: Debris



Code: RMJ

Description: **Roots Medium Joint**

Distance (ft): 59.2 Structural Grade: 0 3 O&M Grade: Clock Start/From: 1 Clock To: 5

1st Value: 2nd Value:

Value Percent: 15.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks:



Code: RMJ

Description: **Roots Medium Joint**


Distance (ft): 69.6 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 1 5 Clock To: 1st Value:

Value Percent: 15.000 Continuous Index: F01 Within 8" of Joint: YES

Remarks:

2nd Value:

Thursday, May 4, 2023



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 81.8
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 10

Clock To: 2

1st Value:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 91.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 94.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 1

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWL

Description: **Water Level**

Distance (ft): 106.7 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

6 Thursday, May 4, 2023



Code: AMH
Description: Manhole

Distance (ft): 162.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-505-043