Profile/Photo Observation Report



Date: 04/21/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 175.3 Owner: NA Pre Clean: No Pre-Cleaning

P.O.#: Surveyor: **Erik Redinger** PSR: **P-505-053.1-053.2**Customer: **Clean Date: 01/01/1900** Shape: **C**

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: MH_F at 33 ft false 2nd attempt . Flow direction wrong

Location Details: Direction of Survey: **Downstream**

US MH: M-505-053.2 DS MH: M-505-053.1 Total Length Surveyed (ft): 34.4

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
и-\$05-05	3.2				
	.0	AMH	Manhole	10	NA
- 11	\0	MWL	Water Level	21	NA
-11	9.2	TF	Tap Factory	51	NA
-11	34.4	MSA	Abandoned Survey	113	NA
Camera Direction					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-505-053.2

 AMH



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO



Code: TF Description: **Tap Factory**

Distance (ft): 9.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MSA

Description: Abandoned Survey

Distance (ft): 34.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: No blockage