


# Profile/Photo Observation Report




Date:	11/02/2021	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	291.8	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-505-059-054
Customer:	City of Hobart	Clean Date:	10/28/2021	Shape:	C

Street:	West 2nd Street	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Local rural streets with light traffic, t	Tape/Media #:	
Purpose:	Routine Assessment	Dia/Height:	10"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Downstream
US MH:	M-505-059	DS MH:	M-505-054
		Total Length Surveyed (ft):	291.8


O&M Index:	1.88	O&M Quick:	3629	O&M Rating:	45.00
Structural Index:	3.30	Structural Quick:	524F	Structural Rating:	208.00
Overall Index:	2.91	Overall Quick:	524F	Overall Rating:	253.00

Position	Code	Observation	Video (sec)	Grade
				
.0	AMH	Manhole	1	NA
.0	MWL	Miscellaneous Water Level	76	NA
4.4	SMW	Surface Damage Missing Wall	143	S 5
4.4	DAE	Deposits Attached Encrustation	171	M 2
4.4	RFJ	Roots Fine Joint	190	M 1
5.1	RML	Roots Medium Lateral	230	M 3
5.4	TFD	Tap Factory Defective	270	M 3
7.5	FM	Fracture Multiple	380	S 4
7.6	RFJ	Roots Fine Joint	415	M 1
8.8	TFC	Tap Factory Capped	445	NA
10.6	DAE	Deposits Attached Encrustation	488	M 2
10.6	FM	Fracture Multiple	552	S 4
10.6	RFJ	Roots Fine Joint	568	M 1
13.6	MWLS(S01)	Miscellaneous Water Level Sag	606	S 2
16.8	RFJ	Roots Fine Joint	647	M 1
16.8	FM(S02)	Fracture Multiple	709	S 4
19.9	RFJ	Roots Fine Joint	771	M 1
20.0	SSS	Surface Damage Surface Spalling	782	S 2
23.1	RFJ	Roots Fine Joint	860	M 1




26.2	RFJ	Roots Fine Joint	895	M 1
26.2	DAE	Deposits Attached Encrustation	925	M 2
29.3	RFJ	Roots Fine Joint	970	M 1
41.5	RFJ	Roots Fine Joint	1052	M 1
48.9	TFD	Tap Factory Defective	1180	M 3
50.9	DAE	Deposits Attached Encrustation	1255	M 2
50.9	DAE	Deposits Attached Encrustation	1291	M 2
51.9	TFD	Tap Factory Defective	1321	M 3
55.3	MWLS(F01)	Miscellaneous Water Level Sag	1358	S 2
72.5	DAE	Deposits Attached Encrustation	1457	M 2
75.0	DR	Deformed Rigid	1502	S 4
75.8	TBD	Tap Break-in/Hammer Defective	1558	M 3
78.4	SSS	Surface Damage Surface Spalling	1596	S 2
96.6	BSV	Broken Soil Visible	1730	S 5
98.2	TFD	Tap Factory Defective	1764	M 3
101.0	TFC	Tap Factory Capped	1797	NA
107.4	TB	Tap Break-in/Hammer	1879	NA
154.8	MWLS(S03)	Miscellaneous Water Level Sag	2102	S 2
160.0	SSS	Surface Damage Surface Spalling	2156	S 2
168.2	FM(F02)	Fracture Multiple	2216	S 4
168.2	DAE	Deposits Attached Encrustation	2224	M 2
179.5	MWLS(F03)	Miscellaneous Water Level Sag	2286	S 2
182.1	SSS	Surface Damage Surface Spalling	2312	S 2
189.7	DAE	Deposits Attached Encrustation	2371	M 2
190.5	CM	Crack Multiple	2388	S 3
225.0	SSS	Surface Damage Surface Spalling	2571	S 2
231.0	CS	Crack Spiral	2612	S 2
246.4	CM(S04)	Crack Multiple	2677	S 3
256.2	SSS	Surface Damage Surface Spalling	2724	S 2
262.7	LD	Line Down	2771	M 2
264.1	JAL	Joint Angular Large	2832	S 4
270.2	JAL	Joint Angular Large	2899	S 4
272.7	CM(F04)	Crack Multiple	2947	S 3
291.8	AMH	Manhole	3171	NA

M-505-054




Code: **AMH**  
 Description: **Manhole**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-505-059**




Code: **MWL**  
 Description: **Miscellaneous Water Level**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **SMW**  
 Description: **Surface Damage Missing Wall**


Distance (ft): **4.4**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From: **6**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **4.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:





Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **4.4**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **11**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RML**  
 Description: **Roots Medium Lateral**

Distance (ft): **5.1**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **10**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent: **35.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **TFD**  
 Description: **Tap Factory Defective**

Distance (ft): **5.4**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **ROOTS GROWING OUT OF THE TAP INTO THE MAIN. LOOKS TO BE 100%**


---



Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **7.5**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To: **9**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:

---



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **7.6**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **TFC**  
 Description: **Tap Factory Capped**


Distance (ft): **8.8**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **CAP LOOKS TO BE FABRIC. ROOTS GROWING AROUND THE CAP**






Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **10.6**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **4**  
 Clock To: **8**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **10.6**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code:	<b>RFJ</b>
Description:	<b>Roots Fine Joint</b>
Distance (ft):	<b>10.6</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>1</b>
Clock Start/From:	<b>1</b>
Clock To:	<b>3</b>
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	




Code:	<b>MWLS</b>
Description:	<b>Miscellaneous Water Level Sag</b>
Distance (ft):	<b>13.6</b>
Structural Grade:	<b>2</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>15.000</b>
Continuous Index:	<b>S01</b>
Within 8" of Joint:	<b>NO</b>
Remarks:	






Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **16.8**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **16.8**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **S02**  
 Within 8" of Joint: **YES**  
 Remarks: **Wandering**




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **19.9**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **2**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **20.0**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **2**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **23.1**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **1**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
 Description: **Roots Fine Joint**


Distance (ft): **26.2**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **26.2**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **29.3**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **RFJ**  
Description: **Roots Fine Joint**


Distance (ft): **41.5**  
Structural Grade: **0**  
O&M Grade: **1**  
Clock Start/From: **1**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:



Code: **TFD**  
Description: **Tap Factory Defective**


Distance (ft): **48.9**  
Structural Grade: **0**  
O&M Grade: **3**  
Clock Start/From: **10**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **OFFSET. ROOTS GROWING FROM THE JOINT AND INTO THE MAIN**





Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **50.9**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **10**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **50.9**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **2**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code:	<b>TFD</b>
Description:	<b>Tap Factory Defective</b>
Distance (ft):	<b>51.9</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>3</b>
Clock Start/From:	<b>1</b>
Clock To:	
1st Value:	<b>4.000</b>
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	<b>SOIL VISIBLE. ROOTS GROWING INTO THE TAP. LOOKS TO BE 100% P</b>

---




Code:	<b>MWLS</b>
Description:	<b>Miscellaneous Water Level Sag</b>
Distance (ft):	<b>55.3</b>
Structural Grade:	<b>2</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>15.000</b>
Continuous Index:	<b>F01</b>
Within 8" of Joint:	<b>NO</b>
Remarks:	

---



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **72.5**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **12**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DR**  
 Description: **Deformed Rigid**

Distance (ft): **75.0**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:






Code: **TBD**  
Description: **Tap Break-in/Hammer Defective**

Distance (ft): **75.8**  
Structural Grade: **0**  
O&M Grade: **3**  
Clock Start/From: **1**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **CONSTANTLY RUNNING WATER.**


---



Code: **SSS**  
Description: **Surface Damage Surface Spalling**


Distance (ft): **78.4**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **BSV**  
 Description: **Broken Soil Visible**


Distance (ft): **96.6**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **TFD**  
 Description: **Tap Factory Defective**

Distance (ft): **98.2**  
 Structural Grade: **0**  
 O&M Grade: **3**  
 Clock Start/From: **11**  
 Clock To:  
 1st Value: **4.000**  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks: **BROKEN. OFFSET. CONSTANTLY RUNNING WATER.**






Code: **TFC**  
Description: **Tap Factory Capped**

Distance (ft): **101.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **TB**  
Description: **Tap Break-in/Hammer**

Distance (ft): **107.4**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **MWLS**  
Description: **Miscellaneous Water Level Sag**

Distance (ft): **154.8**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **S03**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **160.0**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **FM**  
 Description: **Fracture Multiple**


Distance (ft): **168.2**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **F02**  
 Within 8" of Joint: **YES**  
 Remarks: **Wandering**



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **168.2**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **9**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:






Code: **MWLS**  
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **179.5**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **15.000**  
 Continuous Index: **F03**  
 Within 8" of Joint: **NO**  
 Remarks:


---



Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **182.1**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:

---



Code: **DAE**  
Description: **Deposits Attached Encrustation**

Distance (ft): **189.7**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **8**  
Clock To: **9**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **190.5**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **10**  
Clock To: **2**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---





Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **225.0**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **3**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **CS**  
Description: **Crack Spiral**


Distance (ft): **231.0**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **10**  
Clock To: **11**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **246.4**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index: **S04**  
 Within 8" of Joint: **YES**  
 Remarks: **Wandering**



Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **256.2**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **LD**  
Description: **Line Down**

Distance (ft): **262.7**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---




Code: **JAL**  
Description: **Joint Angular Large**

Distance (ft): **264.1**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **SOIL VISIBLE**

---





Code: **JAL**  
Description: **Joint Angular Large**

Distance (ft): **270.2**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **272.7**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **7**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F04**  
Within 8" of Joint: **YES**  
Remarks: **Wandering**

---



Code:	<b>AMH</b>
Description:	<b>Manhole</b>
Distance (ft):	<b>291.8</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	<b>M-505-054</b>