
| Profile/Photo Observation Report | | | | | |
|----------------------------------|-------------------------|--------------------|------------------|---------------------------|-----------------------------|
| Date: Pipe Length (ft | 04/14/2018): | Weather: Owner: | City of Hobart | Coding: Pre Clean: | PACP 6.0 No Pre-Cleaning |
| P.O.#: | 52-2 | Surveyor: | M. Pielacha | PSR: | M-505-055-M-505-054 |
| Customer: | City of Hobart | Clean Date: | | Shape: | С |
| Street: | Colorado Street | | Flow Control: | Not Controlled | 1 |
| City: | Hobart, IN | | Year Renewed: | | |
| Location: | Light Highway | | Tape/Media #: | DEP 52 | |
| Purpose: | Routine Assessment | t | Dia/Height: | 18" | |
| Use: | Sanitary | | Material: | VCP | |
| Drain Area: | | | Lining: | | |
| Category: | NA | | | | |
| Comment: | | | | | |
| Location Detail | ls: | | Direction of Sur | vey: Downstream | |
| US MH: | M-505-055 | DS MH: | M-505-054 | Total Length Surveyed (ft |): 4.2 |
| O&M Index: | 3.50 | O&M Quick: | 413 | 0&M Rating: | 7.00 |
| Structural Index: | 0.00 | Structural Qu | uick: 000 | | 0.00 |
| Overall Index: | 3.50 | Overall Quick | c: 413 | | 7.00 |





| Code: Description: | AMH Manhole |
|-----------------------|----------------|
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-505-055 |

Thursday, May 4, 2023



| Code: | MWL |
|---------------------|-------------|
| Description: | Water Level |
| | |
| Distance (ft): | .0 |
| () | |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 10.000 |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | |
| | |



| Code: Description: | RMJ Roots Medium Joint |
|-----------------------|---------------------------|
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 3 |
| Clock Start/From: | 10 |
| Clock To: | 2 |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 30.000 |
| Continuous Index: | |
| Within 8" of Joint: | YES |
| Remarks: | |
| | |



| Code: | RBJ |
|---------------------|-------------------------|
| Description: | Roots Ball Joint |
| | |
| | 2.6 |
| Distance (ft): | 2.6 |
| Structural Grade: | 0 |
| O&M Grade: | 4 |
| Clock Start/From: | 8 |
| Clock To: | 4 |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 60.000 |
| Continuous Index: | |
| Within 8" of Joint: | YES |
| Remarks: | |
| | |



| Code: Description: | MSA Abandoned Survey |
|-----------------------|-------------------------|
| Distance (ft): | 4.2 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | root ball |