Profile/Photo Observation Report



Date: 04/21/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 268.2 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Mark Ruby PSR: P-505-063-056

Customer: Clean Date: 01/01/1900 Shape: C

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: MH_F at 262 ft false . Just about fell in to D_C . Flow direction wrong

Location Details: Direction of Survey: **Upstream**

US MH: M-505-056 DS MH: M-505-063 Total Length Surveyed (ft): 263.5

1.50 2111 3.00 O&M Index: O&M Quick: O&M Rating: 2.11 3128 19.00 Structural Quick: Structural Rating: Structural Index: 3129 2.00 22.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
505-	063				
\bigvee	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
	23.0	TF	Tap Factory	81	NA
ш	23.0	RFJ	Roots Fine Joint	94	M 1
	36.9	TF	Tap Factory	136	NA
	50.2	CL	Crack Longitudinal	177	S 2
ш	71.1	TF	Tap Factory	233	NA
	81.2	MMC	Material Change	267	NA
	85.0	TF	Tap Factory	291	NA
	91.2	MMC	Material Change	319	NA
ш	114.7	TF	Tap Factory	380	NA
ш	115.7	CL	Crack Longitudinal	396	S 2
Н	126.3	CL	Crack Longitudinal	433	S 2
	128.2	TF	Tap Factory	452	NA
ш	147.1	TF	Tap Factory	503	NA
Ш	155.8	CM	Crack Multiple	535	S 3
ш		CL	Crack Longitudinal	562	S 2
	163.9	CL	Crack Longitudinal	582	S 2
ш	167.1	DAZ	Deposits Attached Other	605	M 2
	175.3	CL	Crack Longitudinal	637	S 2
н	182.4	TF	Tap Factory	666	NA
н	184.7	CL	Crack Longitudinal	684	S 2
ш	190.4	CL	Crack Longitudinal	711	S 2
н	$\sqrt{201.8}$	TF	Tap Factory	748	NA
ш	218.9	TF	Tap Factory	795	NA
	254.7	MMC	Material Change	880	NA
	261.2	TF	Tap Factory	909	NA
	263.5	AMH	Manhole	930	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: M-505-063



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Description: **Tap Factory**

Distance (ft): 23.0 Structural Grade: 0 0 O&M Grade: Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



RFJ Code:

Description: **Roots Fine Joint**

Distance (ft): 23.0 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 7 5 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 36.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 50.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 3
Clock To:
1st Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Description: Tap Factory

Distance (ft): 71.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC

Description: Material Change


Distance (ft): 81.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Description: Tap Factory

Distance (ft): 85.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC

Description: Material Change

Distance (ft): 91.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: VCP



Description: Tap Factory

Distance (ft): 114.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 115.7
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 3
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 126.3
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 4

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 128.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 147.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: CM

Description: Crack Multiple

Distance (ft): 155.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 4
Clock To: 5
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: CL

Description: Crack Longitudinal


Distance (ft): 161.4
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 10

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal


Distance (ft): 163.9
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 3
Clock To:
1st Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 167.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 175.3
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 4
Clock To:
1st Value:
2nd Value:

Continuous Index: Within 8" of Joint:

Value Percent:

thin 8" of Joint: YES



Description: Tap Factory

Distance (ft): 182.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: CL

Description: Crack Longitudinal

4.000



Distance (ft): **184.7**

Structural Grade: 2

O&M Grade: 0

Clock Start/From: 4

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 190.4
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory

Distance (ft): 201.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 218.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: MMC

Description: Material Change

4.000




Distance (ft): 254.7 Structural Grade: 0

O&M Grade: **0**

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Description: Tap Factory

Distance (ft): 261.2
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 6

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: **Drop connection**



Code: AMH
Description: Manhole

Distance (ft): 263.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-505-056