## **Profile/Photo Observation Report**



Date: 04/22/2018 Weather: **PACP 6.0** Coding:

Pipe Length (ft): 321.5 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Jen Costello PSR: P-505-067-070

Customer: Clean Date: 01/01/1900 Shape:

**S WILSON ST** Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Tape/Media #: Location: **Light Highway** 

Purpose: **Routine Assessment** Dia/Height: 10" Use: Sanitary Material: **VCP** 

NA Drain Area: Lining:

NA Category:

Comment: P\_C at 22 ft rocks/debris . Flow direction wrong

**Location Details:** Direction of Survey: Upstream

US MH: M-505-070 Total Length Surveyed (ft): DS MH: M-505-067 23.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
M(505-)00	67				
	.0	AMH	Manhole	10	NA
,	\ <u>.0</u>	MWL	Water Level	21	NA
-	23.9	MSA	Abandoned Survey	81	NA
Camera Direction	70				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:	0
Within 8" of Joint:	NO
Remarks:	M-505-067

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: MSA

Description: **Abandoned Survey** 



Distance (ft): 23.9 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: unknown