



RedZone<sup>®</sup>  
ROBOTICS

Street:	South Wilson Street		Flow Control:	Not Controlled	
City:	City of Hobart		Year Renewed:		
Location:	Local rural streets with light traffic, t		Tape/Media #:		
Purpose:	Routine Assessment		Dia/Height:	10"	
Use:	Sanitary Sewage Pipe		Material:	VCP	
Drain Area:			Lining:	None	
Category:	NA				
Comment:					
Location Details:			Direction of Survey:	Downstream	
US MH:	M-505-070	DS MH:	M-505-067	Total Length Surveyed (ft):	321.9

O&M Index:	<b>2.60</b>	O&M Quick:	<b>4A2B</b>	O&M Rating:	<b>78.00</b>
Structural Index:	<b>2.26</b>	Structural Quick:	<b>4133</b>	Structural Rating:	<b>43.00</b>
Overall Index:	<b>2.47</b>	Overall Quick:	<b>4A33</b>	Overall Rating:	<b>121.00</b>

**Tuesday, April 25, 2023**


116.7	MCU(S02)	Miscellaneous Camera Underwater	1669	M 4
122.6	MCU(F02)	Miscellaneous Camera Underwater	1774	M 4
127.9	MCU(S03)	Miscellaneous Camera Underwater	1862	M 4
127.9	SSS	Surface Damage Surface Spalling	1878	S 2
139.3	MCU(F03)	Miscellaneous Camera Underwater	2068	M 4
141.3	MWL	Miscellaneous Water Level	2113	NA
155.0	MWL	Miscellaneous Water Level	2245	NA
155.0	MCU(S04)	Miscellaneous Camera Underwater	2252	M 4
166.1	MCU(F04)	Miscellaneous Camera Underwater	2425	M 4
169.5	DAE	Deposits Attached Encrustation	2489	M 2
169.5	MWL	Miscellaneous Water Level	2504	NA
175.6	FM	Fracture Multiple	2622	S 4
177.7	RFJ	Roots Fine Joint	2661	M 1
183.6	SSS	Surface Damage Surface Spalling	2710	S 2
185.5	RFJ	Roots Fine Joint	2766	M 1
192.3	SSS	Surface Damage Surface Spalling	2841	S 2
193.4	DAE	Deposits Attached Encrustation	2913	M 2
205.4	DAE	Deposits Attached Encrustation	3015	M 2
211.2	SSS	Surface Damage Surface Spalling	3077	S 2
213.4	DAE	Deposits Attached Encrustation	3141	M 2
229.3	DAE	Deposits Attached Encrustation	3285	M 2
235.6	SSS	Surface Damage Surface Spalling	3363	S 2
241.4	MWL	Miscellaneous Water Level	3450	NA
241.4	MCU(S05)	Miscellaneous Camera Underwater	3462	M 4
241.4	DAE	Deposits Attached Encrustation	3493	M 2
251.7	MCU(F05)	Miscellaneous Camera Underwater	3646	M 4
253.2	CL	Crack Longitudinal	3684	S 2
255.3	CS	Crack Spiral	3760	S 2
257.2	JAM	Joint Angular Medium	3810	S 3
261.0	MWL	Miscellaneous Water Level	3865	NA
266.1	SSS	Surface Damage Surface Spalling	3907	S 2
280.1	MWL	Miscellaneous Water Level	4003	NA
281.3	DAE(S06)	Deposits Attached Encrustation	4044	M 2
296.0	SSS	Surface Damage Surface Spalling	4160	S 2
320.3	DSC	Deposits Settled Hard/Compacted	4347	M 2
320.3	DAE(F06)	Deposits Attached Encrustation	4358	M 2
321.9	AMH	Manhole	4463	NA

M-505-067



Code: **AMH**  
 Description: **Manhole**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-505-070**



Code: **MWL**  
 Description: **Miscellaneous Water Level**


Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **DAE**  
Description: **Deposits Attached Encrustation**

Distance (ft): **30.4**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **8**  
Clock To: **11**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **DAE**  
Description: **Deposits Attached Encrustation**


Distance (ft): **34.2**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **12**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **MWL**  
 Description: **Miscellaneous Water Level**

Distance (ft): **46.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **20.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **SSS**  
 Description: **Surface Damage Surface Spalling**


Distance (ft): **49.2**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **12**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **53.7**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **10**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **JAM**  
Description: **Joint Angular Medium**


Distance (ft): **58.1**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---




Code: **ISSRH**  
 Description: **Intruding Sealing Material Sealing Ring Hanging**

Distance (ft): **70.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **10**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **70.3**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **78.4**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **11**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWL**  
 Description: **Miscellaneous Water Level**


Distance (ft): **82.3**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **35.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**

Distance (ft): **82.3**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S01**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**


Distance (ft): **98.9**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F01**  
Within 8" of Joint: **NO**  
Remarks:

---




Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **105.9**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **MWL**  
 Description: **Miscellaneous Water Level**


Distance (ft): **107.3**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **20.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **109.4**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **11**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **112.3**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **116.7**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **35.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**

Distance (ft): **116.7**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S02**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**

Distance (ft): **122.6**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F02**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**


Distance (ft): **127.9**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S03**  
Within 8" of Joint: **NO**  
Remarks:

---




Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **127.9**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**


Distance (ft): **139.3**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F03**  
Within 8" of Joint: **NO**  
Remarks:



Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **141.3**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **155.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **35.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**

Distance (ft): **155.0**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S04**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**

Distance (ft): **166.1**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F04**  
Within 8" of Joint: **NO**  
Remarks:


---



Code:	<b>DAE</b>
Description:	<b>Deposits Attached Encrustation</b>
Distance (ft):	<b>169.5</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>2</b>
Clock Start/From:	<b>2</b>
Clock To:	<b>3</b>
1st Value:	
2nd Value:	
Value Percent:	<b>5.000</b>
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	




Code:	<b>MWL</b>
Description:	<b>Miscellaneous Water Level</b>
Distance (ft):	<b>169.5</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>15.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	




Code: **FM**  
 Description: **Fracture Multiple**

Distance (ft): **175.6**  
 Structural Grade: **4**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **5**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **177.7**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **10**  
 Clock To: **12**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **183.6**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **10**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **RFJ**  
 Description: **Roots Fine Joint**

Distance (ft): **185.5**  
 Structural Grade: **0**  
 O&M Grade: **1**  
 Clock Start/From: **9**  
 Clock To: **1**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:




Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **192.3**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **3**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**


Distance (ft): **193.4**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **9**  
 Clock To: **3**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
Description: **Deposits Attached Encrustation**

Distance (ft): **205.4**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **9**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **211.2**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **DAE**  
Description: **Deposits Attached Encrustation**

Distance (ft): **213.4**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **9**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **DAE**  
Description: **Deposits Attached Encrustation**

Distance (ft): **229.3**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **9**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **SSS**  
Description: **Surface Damage Surface Spalling**

Distance (ft): **235.6**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **11**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **241.4**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **35.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MCU**  
Description: **Miscellaneous Camera Underwater**

Distance (ft): **241.4**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S05**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **DAE**  
Description: **Deposits Attached Encrustation**


Distance (ft): **241.4**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **10**  
Clock To: **2**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code:	<b>MCU</b>
Description:	<b>Miscellaneous Camera Underwater</b>
Distance (ft):	<b>251.7</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>4</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	<b>F05</b>
Within 8" of Joint:	<b>NO</b>
Remarks:	

---




Code:	<b>CL</b>
Description:	<b>Crack Longitudinal</b>
Distance (ft):	<b>253.2</b>
Structural Grade:	<b>2</b>
O&M Grade:	<b>0</b>
Clock Start/From:	<b>12</b>
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>YES</b>
Remarks:	

---




Code: **CS**  
 Description: **Crack Spiral**

Distance (ft): **255.3**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **9**  
 Clock To: **11**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **JAM**  
 Description: **Joint Angular Medium**


Distance (ft): **257.2**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **261.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **SSS**  
Description: **Surface Damage Surface Spalling**


Distance (ft): **266.1**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **2**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---




Code: **MWL**  
 Description: **Miscellaneous Water Level**

Distance (ft): **280.1**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **281.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **S06**  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **SSS**  
 Description: **Surface Damage Surface Spalling**

Distance (ft): **296.0**  
 Structural Grade: **2**  
 O&M Grade: **0**  
 Clock Start/From: **1**  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks:




Code: **DSC**  
 Description: **Deposits Settled Hard/Compacted**

Distance (ft): **320.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **5**  
 Clock To: **7**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DAE**  
 Description: **Deposits Attached Encrustation**

Distance (ft): **320.3**  
 Structural Grade: **0**  
 O&M Grade: **2**  
 Clock Start/From: **8**  
 Clock To: **4**  
 1st Value:  
 2nd Value:  
 Value Percent: **5.000**  
 Continuous Index: **F06**  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **AMH**  
 Description: **Manhole**

Distance (ft): **321.9**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-505-067**